POOR LEGIBILITY

ONE OR MORE PAGES IN THIS DOCUMENT ARE DIFFICULT TO READ DUE TO THE QUALITY OF THE ORIGINAL

SFUND RECORDS CTR 2238204

CH2M HILL

155 Grand Avenue, Suite 800

Oakland, CA 94612

P.O. Box 12681

Oakland, CA 94604-2681

Tel 510.251.2426

Fax 510.622.9000

July 9, 2010 264204.16.A2.03/MIC2SS417

Ms. Janet Naito California Environmental Protection Agency Department of Toxic Substances Control 700 Heinz Avenue, Suite 200 Berkeley, CA 94710-2721

Mr. Erich Simon California Regional Water Quality Control Board San Francisco Bay Region 1515 Clay Street, Suite 1400 Oakland, CA 94612

Subject: Site Summary Report for the Storm Sewer System near IR19, IR21/Buildings

386/388/390 Area, PCB Site Building 678 AL#04 and PCB Site Building 830 UL#01 in Investigation Area C2, Lennar Mare Island, Vallejo, California

Dear Ms. Naito and Mr. Simon:

Enclosed is a copy of the Site Summary Report for the Storm Sewer System near IR19, IR21/Buildings 386/388/390 Area, PCB Site Building 678 AL#04 and PCB Site Building 830 UL#01 in Investigation Area C2, Lennar Mare Island, Vallejo, California.

This document was prepared by CH2M HILL on behalf of Lennar Mare Island, LLC (LMI), as part of the scope of the Environmental Services Cooperative Agreement to complete remaining environmental work at Mare Island, and in accordance with the Consent Agreement between LMI, City of Vallejo, and the California Environmental Protection Agency, Department of Toxic Substances Control.

Please submit your comments to me at the above address or via e-mail at <u>Stephen.Farley@ch2m.com</u> by August 9, 2010.

lin Jailey

If you have any questions regarding this document, please contact me at 707/562-1015 extension 103 or Paula Bolio at 510/587-7748.

Sincerely,

CH2M HILL

Stephen M. Farley, P.G. Senior Technical Consultant RDD/101890027 (CAH4707.doc) Ms. Janet Naito Mr. Erich Simon July 9, 2010 Page 2

Copy to (with enclosures):

Ms. Carolyn d'Almeida U.S. EPA Region 9 (SFD 8-1) 75 Hawthorne Street, 9th Floor San Francisco, CA 94105

Mr. Neal Siler Lennar Mare Island, LLC 690 Walnut Avenue, Suite 100 Vallejo, CA 94592 (Electronic copy also)

Mr. Mike Mentink Caretaker Site Office, SF Bay 1 Avenue of the Palms, Suite 161 San Francisco, CA 94130 (2 copies)

Ms. Sheila Roebuck Lennar Mare Island, LLC 690 Walnut Avenue, Suite 100 Vallejo, CA 94592 (Electronic copy of IAB.1, H2, and IA D1.3 only)

Mr. John Catts 130 Camino Margarita Nicasio, CA 94946 (Electronic copy only)

William Bir Zurich 560 Mission Street, Suite 2300 San Francisco, CA 94105 (Electronic copy only)

CH2M HILL copies:

Paula Bolio Clemena Balbuena Tim Graves (Electronic copy only) Ed Aromi (Electronic copy only) Mr. Gil Hollingsworth 555 Santa Clara Street Vallejo, CA 94590-5934 (Electronic copy only)

Mr. Gordon Hart Paul, Hastings, Janofsky, Walker, LLP 55 Second Street, 24th Floor San Francisco, CA 94105-3411

Ms. Myrna Hayes 816 Branciforte Street Vallejo, CA 94590

Mr. Michael F. McGowan, Ph.D. Arc Ecology 4634 – 3rd Street San Francisco, CA 94124 (Electronic copy only)

Ms. Kanan Sheth Zurich North America Specialties P.O. Box 307010 Jamaica, NY 11430-7010 (Electronic copy only)

Ms. Karen Lubovinsky 449 Union School Rd, Ste 101 Oxford, PA 19363 (Electronic copy only) Ms. Janet Naito Mr. Erich Simon July 9, 2010 Page 3

Copy to (without enclosures):

Ms. Janet Whitlock U.S. Fish and Wildlife Service 2800 Cottage Way, Room W-2605 Sacramento, CA 95825 Mr. Justice Budu 107 Fieldstone Way Vallejo, CA 94589

Ms. Laurie Sullivan
National Oceanic and Atmospheric
Administration
75 Hawthorne Street, 9th Floor
San Francisco, CA 94105
(Electronic copy only via email)

Mr. Mike Coffey 6 Oricle Court American Canyon, CA 94503

Mr. Ron Pilkington Bay Area Air Quality Management District 939 Ellis Street San Francisco, CA 94109 Mr. James O'Loughlin 1449 Sheridan Drive Napa, CA 94558

Mr. Kenneth Browne 109 El Camino Real Vallejo, CA 94590

Mr. Max Delaney San Francisco Bay Commission 50 California Street, Suite 2600 San Francisco, CA 94102

Mr. Adam A. Chavez 1031 Florida Street Vallejo, CA 94590-5513 Mr. Terry Schmidtbauer Dept. of Resource Management County of Solano 675 Texas Street, Suite 5500 Fairfield, CA 94533

Mr. Gerald Karr 149 Garden Court Vallejo, CA 94591 Mr. Russell S. Sherman Vallejo Fire Department 970 Nimitz Avenue Vallejo, CA 94592

Ms. Paula Tygielski 456 East L Street Benicia, CA 94510 Site Summary Report for the Storm Sewer System near IR19, IR21/Buildings 386/388/390 Area, PCB Site Building 678 AL#04, and PCB Site Building 830 UL#01 in Investigation Area C2, Lennar Mare Island, Vallejo, California

Prepared for Regulatory Agencies

July 2010

CH2MHILL

155 Grand Avenue Suite 1000 Oakland, CA 94612

Site Summary Report for the Storm Sewer System near IR19, IR21/Buildings 386/388/390 Area, PCB Site Building 678 AL#04, and PCB Site Building 830 UL#01 in Investigation Area C2, Lennar Mare Island, Vallejo, California

This report was prepared under the direct supervision of a Professional Engineer and a Professional Geologist registered with the State of California, whose signatures appear below.

PROFESSIONAL STATE OF THE PROPERTY OF THE PROP	
No. C-047003	
of carried 2/4/200	

David Allard, P.E. Civil Engineer CH2M HILL

Date: 7 9 STEPHEN FARLEY FARLEY Professional Geologis CALCUS CH2M HILL

Date: 2/9/10

Prepared by:

CH2M HILL

Contents

			Page
Acro	nyms a	nd Abbreviations	VII
1.0	Intro	ductionduction	1-1
	1.1	Purpose	1-1
	1.2	Background	1-1
		1.2.1 PCB Site Building 535 AL#01	1-3
		1.2.2 IR19	1-4
		1.2.3 IR21/Buildings 386/388/390 Area	1-4
		1.2.4 PCB Site Building 678 AL#04	1-4
		1.2.5 PCB Site Building 830 UL#01	1-4
	1.3	Report Organization	1-5
2.0	-	oling Activities, Applicable Screening Level Criteria, and Results	
	2.1	IR19	
		2.1.1 Sampling Activities	
		2.1.2 Screening-level Criteria	
	2.2	2.1.3 Results	
	2.2	IR21/Buildings 386/388/390 Area	
		2.2.1 Sampling Activities	
		2.2.2 Screening-level Criteria	
	2.2	2.2.3 Results	
	2.3	PCB Site Building 678 AL#04	
		2.3.1 Sampling Activities	
		2.3.2 Screening-level Criteria	
	0.4	2.3.3 Results	2-4
	2.4	PCB Site Building 830 UL#01	
		2.4.1 Sampling Activities	
		2.4.2 Screening-level Criteria	
		2.4.3 Results	
3.0		/Buildings 386/388/390 Area Cleaning Activities	
	3.1	Cleaning Activities and Cleanup Objectives	
	3.2	Subcontractors	
	3.3	Summary of Cleaning Activities	
_		3.3.1 Pre-cleaning Activities – CCTV Video Inspection	
	1	3.3.2 Pre-cleaning Activities – Site Reconnaissance	3-3
	,	3.3.3 Stormwater Drainage around the IR21/Buildings 386/388/390 Area	3-3
		3.3.4 Storm Sewer System Cleaning Activities	
		3.3.5 Sample Collection	
		3.3.6 Pipeline Tracer Video Inspection at CB3	
		3.3.7 Post-cleaning CCTV Video Inspection	
	3.4	Results of Cleaning Activities	

Contents, Continued

		\mathbf{P}	age
	3.5	Evaluation of Soil and Groundwater Along Broken Pipeline Segment (MH4 to MH5)	3-6
	3.6	Waste Management	
4.0	Conc 4.1 4.2	Clusions and Criteria for Obtaining Site Closure Conclusions Criteria for No Further Action	4-1
5.0	Refe	rences	5-1
Appe	ndices	;	
A	Colle	lytical Results for Sediment, Concrete Chip, and/or Rinsate Water Samples ected from the Storm Sewer System near IR19, IR21/Buildings 386/388/390, PCB Site Building 678 AL#04, and PCB Site Building 830 UL#01	
В.	Unva	alidated Laboratory Analytical Reports	
C	Rinsa Syste	ate Wastewater Analytical Results and Permit to Discharge to Sanitary Sewer em	r
D	Was	te Profile and Waste Disposal Manifest	
Table	es	· · · · · · · · · · · · · · · · · · ·	
1-1		Identification Technical Memorandum Conclusions and Agency roval	1-2
3-1		lytical Results for Rinsate Water Samples Following Storm Sewer em Cleaning Activities near the IR21/Buildings 386/388/390 Area	3-6
;	· v	•	
Figur	es		
1-1	Easte	ern Early Transfer Parcel Location Map	1-6
1-2	PCE	in Sediment and Water at the Storm Sewer System near IR19	1-7
1-3		l, TPH-Diesel, and TPH-Motor Oil and PCB Concentrations in Sediment e Storm Sewer System near IR21/Buildings 386/388/390 Area	1-8
1-4		Concentrations in Sediment and Concrete at the Storm Sewer System PCB Site Building 678 AL#04	1-9

Contents, Continued

	•	Page
1-5	PCB Concentrations in Concrete at the Storm Sewer System near PCB Site Building 830 UL#01	1-10
3-1	Lead, TPH-Diesel, and TPH-motor-oil Concentrations in Rinsate Samples at the Storm Sewer Pipeline Near the IR21/Buildings 386/388/390 Area	3-8
3-2	TPH-Diesel and TPH-motor-oil Concentrations in Soil and Groundwater near the Broken Pipeline Segment at the Storm Sewer System near IR21/Buildings 386/388/390 Area	3-9
3-3	Lead and PCB Concentrations in Soil and Groundwater near the Broken Pipeline Segment at the Storm Sewer System Near the IR21/ Buildings 386/388/390 Area	3-10

Acronyms and Abbreviations

μg/L micrograms per liter

bgs below ground surface

CB catch basin

CCTV closed-circuit television

COC constituent of concern

DTSC State of California Environmental Protection Agency, Department of Toxic

Substances Control

EETP Eastern Early Transfer Parcel

IA Investigation Area

ICS Innovative Construction Solutions

IR Installation Restoration

IT IT Corporation

J Estimated concentration

LMI Lennar Mare Island, LLC

LUC land use covenant

mg/kg milligrams per kilogram

MH manhole

Navy United States Department of Navy

PCB polychlorinated biphenyl

PCE tetrachloroethene

RSL regional screening level

TPH total petroleum hydrocarbons

USEPA United States Environmental Protection Agency

VOC volatile organic compound

VSFCD Vallejo Sanitation and Flood Control District

Water Board California Regional Water Quality Control Board, San Francisco Bay Region

Y Fuel Pattern (TPH only)

1.0 Introduction

CH2M HILL prepared this Site Summary Report on behalf of Lennar Mare Island, LLC (LMI) for the storm sewer system located near Installation Restoration Program Site (IR) 19 (IR19), the IR21/Buildings 386/388/390 Area, Polychlorinated Biphenyl (PCB) Site Building 678 AL#04 and PCB Site

Building 830 UL#01 in Investigation Area (IA) C2, Lennar Mare Island, Vallejo, California. This report was prepared in accordance with the Consent Agreement (LMI et al. 2001) signed April 16, 2001, by LMI, the City of Vallejo, and the State of California Environmental Protection Agency, Department of Toxic Substances Control (DTSC).

1.1 Purpose

This Site Summary Report summarizes the investigations and cleaning actions performed for the storm sewer system near the sites listed above in IA C2 at the Eastern Early Transfer Parcel (EETP) of the former Mare Island Naval Shipyard. The location of the EETP is shown in Figure 1-1. In addition, this Site Summary Report provides the information necessary to support the conclusion that additional investigation/remedial activities are not required for the storm sewer system near these sites.

1.2 Background

The storm sewer system at the EETP is a network of catch basins (CBs), manholes (MHs), and pipelines to handle surface water runoff, which is then discharged to Mare Island Strait or the west side of Mare Island at several outfall locations. Before 1959, sanitary and industrial wastes were discharged to the storm sewer system.

The storm sewer system was constructed of vitrified clay pipe, corrugated metal pipe, asphalt-coated corrugated metal pipe, transite concrete, reinforced concrete pipe, and sections of other materials. The MHs and CBs vary in depth, size, shape, and construction materials. CBs were designed as shallow basins with sediment traps. Many of the older CBs and MHs are constructed of brick, whereas some of the newer basins are made of concrete. The features and condition of the storm sewer system were described in *Final Post-Construction Report Storm Drain Cleaning, Former Mare Island Naval Shipyard Vallejo, California* (IT Corporation 2002). As described in that report, the pipelines range from good to poor, and several contain cracks, separated joints, damaged mortar, and leaking joints. Portions of the storm sewer pipelines nearest the Mare Island Strait are also tidally influenced, and many of the outfalls do not have tidal gates (IT Corporation 2002). The storm sewer system at the EETP is currently operated by the Vallejo Sanitation and Flood Control District (VSFCD).

The storm sewer system was evaluated for IAs within the EETP that have not yet received no further action certification. The storm sewer system in these IAs was discussed in the Site Identification Technical Memoranda (CH2M HILL 2002a-e, 2003). Table 1-1 lists the

conclusions of the respective technical memoranda and the agency approval letters, where applicable.

TABLE 1-1
Site Identification Technical Memorandum Conclusions and Agency Approval
Site Summary Report for the Storm Sewer System Near IR19, IR21/Buildings 386/388/390 Area, PCB Site Building 678
AL#04, and PCB Site Building 830 UL#01 in Investigation Area C2, Lennar Mare Island, Vallejo, California

IA	Site Building 830 OL#01 in Investigation Area C2, Lennar Mare Island, Vallejo, California Site Identification Technical Memorandum Conclusion and Date of Agency Approval
B.1, B.2-1 and B.2-2	The Final Investigation Area B Site Identification Technical Memorandum (CH2M HILL 2002a) concluded that the storm sewer system would not be carried forward as a site of environmental concern.
	DTSC approved this report on January 15, 2003 (DTSC 2003a). Water Board deferred approval of this report to DTSC during an agency meeting on December 17, 2002 (CH2M HILL 2002f).
C1	The Final Investigation Area C1 Site Identification Technical Memorandum (CH2M HILL 2002b) concluded that the storm sewer system would not be carried forward as a site of environmental concern.
	DTSC approved this report on February 20, 2003 (DTSC 2003b). Water Board approved the Final Investigation Area C2 Site Identification Technical Memorandum by approving the Final IA C1 Remedial Investigation/Feasibility Study Report (CH2M HILL 2006a) on February 4, 2009 (Water Board 2009).
C2	The Final Investigation Area C2 Site Identification Technical Memorandum (CH2M HILL 2002c) concluded that the storm sewer system would not be carried forward as a site of environmental concern.
	DTSC approved this report on May 20, 2003 (DTSC 2003c). Water Board approved this report with exception to Building 862 and 868 on February 13, 2003 (Water Board 2003a). These two sites (Oil House Site 862 and 868) are petroleum sites that are separately addressed under the underground storage tank program in accordance with Water Board Order R2-2002-0105.
C3	The Final Investigation Area C3 Site Identification Technical Memorandum (CH2M HILL 2002d) concluded that, other than the storm sewer system located between Dry Dock No. 1 and Dry Dock No. 2 (discussed below), there are no other sites of environmental concern associated with the storm sewer system.
	DTSC approved this report on January 17, 2003 (DTSC 2003d). Water Board approved this report on January 8, 2003 (Water Board 2003b).
D.1-3	The Final Investigation Area D1 Site Identification Technical Memorandum (CH2M HILL 2003) concluded that the storm sewer system would not be carried forward as a site of environmental concern.
	DTSC approved this report on November 6, 2003 (DTSC 2003e). Water Board approved this report on November 4, 2003 (Water Board 2003c).
H2	The Final Investigation Area H2 Site Identification Technical Memorandum (CH2M HILL 2002e) concluded that the storm sewer system would not be carried forward as a site of environmental concern.
	DTSC approved this report on January 10, 2003 (DTSC 2003f). Water Board approved this report on January 8, 2003 (Water Board 2003d).

As mentioned in Table 1-1, the storm sewer system between Dry Dock No. 1 and Dry Dock No. 2 in IA C3 was identified as a site of environmental concern in the *Final Investigation Area C3 Site Identification Technical Memorandum* (CH2M HILL 2002d). The storm sewer system in this area is addressed as part of PCB Site Building 516 AL#01. Selected storm

sewer CBs, MHs, and portions of the storm sewer pipelines at PCB Site Building 516 AL#01 were inspected and removed as documented in the *Site Characterization and Cleanup Action Summary Report for Polychlorinated Biphenyl Sites Building 516 and 516A Investigation Area C3, Lennar Mare Island, California* (CH2M HILL 2007) and "Response to Department of Toxic Substances Control Comments on the Site Characterization and Cleanup Action Summary Report for the Storm Sewer System near Polychlorinated Biphenyl Site Building 516 AL#01, Investigation Area C3, Lennar Mare Island, Vallejo, California" (CH2M HILL 2009a). DTSC issued closure approval for PCB Site Building 516A UL#01 on July 18, 2007 (DTSC 2007a) and Building 516 AL#01 on April 22, 2009, pending recordation of a land use covenant (LUC) restricting the site to industrial/commercial uses (DTSC 2009a). The United States Environmental Protection Agency (USEPA) issued closure approval for PCB Site Buildings 516 AL#01 and 516A AL#01 on August 31, 2009 (USEPA 2009a); therefore, this site is not addressed in this Site Summary Report.

Following the issuance of the IA Site Identification Technical Memoranda, the storm sewer system located immediately downgradient of the following sites was identified for further evaluation:

- PCB Site Building 535 AL#01
- IR19
- IR21/Buildings 386/388/390 Area
- PCB Site 678 AL#04
- PCB Site Building 830 UL#01

1.2.1 PCB Site Building 535 AL#01

One MH downstream of the storm sewer system associated with PCB Site Building 535 AL#01 is located within IA B.2-1. A concrete chip sample from this MH had a reported total PCB concentration of 2 milligrams per kilogram (mg/kg). DTSC requested additional investigation of the storm sewer system near Building 535 AL#01 in comments to the Site Characterization and Cleanup Summary Report for PCB Site At Building 535 AL#01 and AL#02 in Investigation Area B.2 (CH2M HILL 2008) on March 25, 2008 (DTSC 2008). Remedial actions at PCB Site Building 535 AL#01 are being performed in accordance with the "Addendum to the Cleanup Plan for Polychlorinated Biphenyl Site Building 535 AL#01 in Investigation Area B.2" (CH2M HILL 2009b) and "Addendum to the Notification Regarding Self-implementing, Onsite Cleanup and Disposal of Polychlorinated Biphenyl Remediation Waste at Polychlorinated Biphenyl Site Building 535 AL#01 in Investigation Area B.2" (CH2M HILL 2009c). Future actions, if necessary, may be included in "Addendum to the Site Characterization and Cleanup Action Summary Report for Polychlorinated Biphenyl Sites Building 535 AL#01, Investigation Area B.2" (CH2M HILL pending(a)). Following completion of remedial actions at PCB Site Building 535 AL#01, an implementation report will be submitted to DTSC and the USEPA documenting work performed and requesting closure of PCB Site Building 535 AL#01 and the associated storm sewer system. In addition, a PCB-specific LUC will be implemented at this site to prohibit sensitive land uses. Therefore, this site is not addressed in this Site Summary Report.

1.2.2 IR19

During storm sewer system sampling and cleaning activities performed at the EETP by IT Corporation for the Department of the Navy (Navy) in 2000 (IT Corporation 2002), tetrachloroethene (PCE) was detected in sediment (18.5 mg/kg) and water (1,610 micrograms per liter [μ g/L]) collected from MH D1-M13 (sample locations SD-002 and W-002, respectively, in Figure 1-2). The sediment and water were subsequently removed by IT Corporation in 2001 (IT Corporation 2002). MH D1-M13 is located at the southern boundary of IR19, as shown in Figure 1-2. DTSC requested additional characterization of MH D1-M13 to address this historical detection of PCE in sediment and water during a telephone conversation with CH2M HILL on January 14, 2009 (DTSC 2009b). On the basis of these results, this site is discussed further in this Site Summary Report.

1.2.3 IR21/Buildings 386/388/390 Area

As part of the storm sewer system sampling and cleaning activities performed by IT Corporation for the Navy in 2001 (IT Corporation 2002), sediment and water were removed from CBs and MHs located downgradient and across Railroad Avenue from the IR21/Buildings 386/388/390 Area. Sediment and water were not removed from CBs and MHs adjacent to the site. In comments to the *Draft Removal Action Work Plan for the IR21 Area, Lennar Mare Island, Vallejo, California* (CH2M HILL 2006b), DTSC requested more information regarding the storm sewer system near the IR21/Buildings 386/388/390 Area (DTSC 2007b). The location of the IR21/Buildings 386/388/390 Area is shown in Figure 1-3. On the basis of this request for information, this site is discussed further in this Site Summary Report.

1.2.4 PCB Site Building 678 AL#04

PCB Site Building 678 AL#04 is an active outdoor transformer pad located west of Building 678, as shown in Figure 1-4. As part of the PCB program, a sediment sample (B678AL04-0809) was collected in June 2004 from the bottom of the adjacent CB B678GB1 located at the southwest corner of the transformer pad. Although Figure 1-4 shows that the sample B678AL04-0809 was collected at 0 feet below ground surface (bgs), this sample was collected from sediment that had accumulated in the bottom of the storm sewer B678GB1 at 3 feet bgs, as summarized in *Site Characterization and Cleanup Action Summary Report for Polychlorinated Biphenyl Site Building 678 AL#04, Investigation Area C2, Lennar Mare Island, Vallejo, California* (CH2M HILL pending(b)), the total PCB concentration in this sediment sample was 0.95 mg/kg, which exceeded the USEPA Region 9 industrial regional screening level (RSL) of 0.74 mg/kg for total PCBs in soil (USEPA 2009b). On the basis of these results, this site is discussed further in this Site Summary Report.

1.2.5 PCB Site Building 830 UL#01

PCB Site Building 830 UL#01 is an electrical substation located inside of Building 830. Because this site is located in an enclosing cinder block structure that has no roof and contains drain holes, it is considered an outdoor structure with potential to impact downgradient CBs/MHs. As discussed in the Polychlorinated Biphenyl Site Building 830 UL#01 (Electric Substation 22) in Investigation Area C2, Where No Further Action Is Required under the Department of Toxic Substances Control Consent Agreement and Polychlorinated


Biphenyl Site Building 830 UL#01 (Electric Substation 22) in Investigation Area C2, Where No Further Action Is Required under the United States Environmental Protection Agency Consent Agreement and Final Order (CH2M HILL 2009d-e), this electric substation once contained PCBs in transformer oil and concrete chip samples with concentrations up to 271 mg/kg and 6.95 mg/kg (sample location 7294-0253 in Figure 1-5), respectively. The nearest CB (B830CB1) to PCB Site Building 830 UL#01 is located south of Building 830, shown in Figure 1-5. On the basis of these results, this site is discussed further in this Site Summary Report.


1.3 Report Organization


This Site Summary Report is organized into the following sections:


- **Section 1.0, Introduction,** presents the background and a brief overview of the contents of this document.
- Section 2.0, Storm Sewer System Sampling Activities, Applicable Screening Level Criteria, and Results summarizes the storm sewer system sampling activities, screening level criteria, and sample results for each of the storm sewer sites evaluated in IA C2.
- Section 3.0, IR21 Buildings 386/388/390 Area Cleaning Activities, outlines cleanup criteria and summarizes cleaning activities, results, and post-cleanup activities.
- Section 4.0, Conclusions and Criteria for Obtaining Site Closure, summarizes the rationale for site closure.
- Section 5.0, References, presents references for documents used to prepare this Site Summary Report.











2.0 Sampling Activities, Applicable Screening Level Criteria, and Results

CH2M HILL initiated the storm sewer CB and MH sampling activities in March 2009 near the sites in IA C2 discussed in Section 1.2.2 through 1.2.5. Because PCB Site Building 535 AL#01 and PCB Site Building 516 AL#01 are separately addressed under the PCB Program, the storm sewer system sampling activities included CBs and MHs located immediately downgradient of IR19, IR21/Buildings 386/388/390 Area, PCB Site Building 678 AL#04, and PCB Site Building 830'UL#01. The storm sewer system sampling consisted of an initial round of sediment or concrete chip sampling and analysis. If sediment was present, a composite sample was collected from accumulated sediments in the bottom of the CB or MH and was submitted for analysis of the known constituents of concern (COCs) encountered at the immediately upgradient site. Concrete chip samples were collected from the bottom of the CBs at sites immediately downgradient of PCB sites. If the analytical results of the first round of sampling exceeded screening levels then step-out sampling to CBs/MHs located along the storm sewer pipeline was performed to evaluate the concentrations of COCs downgradient in the pipeline. Additional information regarding the storm sewer system sampling activities and the results for the four sites described above are provided below. CH2M HILL-validated analytical results are included Appendix A, and the unvalidated laboratory analytical reports are included in Appendix B.

The sampling activities described below were presented to DTSC and Water Board during an agency meeting on February 10, 2009 (CH2M HILL 2009f). DTSC and Water Board verbally approved CH2M HILL's sampling plan, including screening criteria, during this meeting. DTSC also approved the sampling activities in an email dated December 9, 2009 (DTSC 2009c).

2.1 IR19

2.1.1 Sampling Activities

Based on DTSC's request to address the historical detection of PCE in sediment and water in MH D1-M13 (DTSC 2009b), CH2M HILL collected a composite sample (IR19D1M13SD0101) from accumulated sediments in the bottom of MH D1-M13 at 7 feet bgs in March 2009 (Figure 1-2). The sediment sample was analyzed for volatile organic compounds (VOCs), including PCE (USEPA Method 8260B).

2.1.2 Screening-level Criteria

The analytical results for VOCs in the sediment sample were compared to the USEPA industrial RSLs (USEPA 2009b).

2.1.3 Results

VOCs in the sediment sample collected from the bottom of MH D1-M13 (IR19D1M13SD0101) were not detected above laboratory reporting limits. In addition, laboratory reporting limits did not exceed USEPA industrial RSLs. Specifically, the PCE concentration (0.0026mg/kg) did not exceed the USEPA industrial RSL of 2.7 mg/kg (USEPA 2009b). Therefore, additional investigation / remedial activities are not required for the storm sewer system near IR19. The sample results and request for no additional investigation/remedial activities for the storm sewer system near IR19 were presented to DTSC and the Water Board during an agency meeting on April 28, 2009 (CH2M HILL 2009e). DTSC and Water Board verbally approved no additional investigation/remedial activities are required for the storm sewer system near IR19 during this agency meeting. DTSC also approved no additional investigation / remedial activities are necessary for the storm sewer system near IR19 via an email on December 9, 2009 (DTSC 2009c).

2.2 IR21/Buildings 386/388/390 Area

2.2.1 Sampling Activities

To address DTSC's comments (DTSC 2007b) to the Draft Removal Action Work Plan for the IR21 Area (CH2M HILL 2006b), CH2M HILL collected a composite sample (IR21CB1SD0101) from accumulated sediments in the bottom of IR21CB1, located between Building 382 and Building 390 west of Railroad Avenue (Figure 1-3), in March 2009. This location was selected because it is located at a storm sewer pipeline junction that receives water from pipelines running along the east side of Building 390 and along the south side of Buildings 386/388/390. The sediment sample was collected at 6 feet bgs and was submitted for analysis of total petroleum hydrocarbons (TPH) as diesel (TPH-diesel) and TPH as motor oil (TPH-motor-oil) using USEPA Method 8015B, for lead using USEPA Method 6010B, and for PCBs using USEPA Method 8082. Analysis was based on the known COCs identified for the IR21/Buildings 386/388/390 Area in the Final Feasibility Study/Removal Action Work Plan for IR21 and the Buildings 386/388/390 Area, Investigation Area C2, Lennar Mare Island, Vallejo, California (CH2M HILL 2009g). Based on the analytical results found in the sediment sample collected from CB IR21CB1, step-out sampling along the storm sewer pipeline interior was performed in April and May 2009. The step-out sampling was performed at two upgradient CBs (IR21CB2 and IR21CB3), one upgradient MH (IR21MH2), and one downgradient CB (IR21CB4) located along the storm sewer pipelines. Composite sediment samples (IR21CB2SD0101, IR21CB3SD0101, and IR21MH2SD0101 at 3 feet bgs and IR21CB4SD0101 at 6 feet bgs) were collected from accumulated sediments in the bottom of the CBs and MH.

2.2.2 Screening-level Criteria

The analytical results for TPH-diesel and TPH-motor-oil in the sediment samples were compared to Tier 2 screening levels for shallow soils (0 to 3 feet bgs) at sites located greater than 300 feet of a sensitive receptor (i.e., Mare Island Strait) (CH2M HILL 2009h). The analytical results for lead and PCBs in sediment samples were compared to the USEPA industrial RSL for lead and PCBs in soil (USEPA 2009b).

2.2.3 Results

The concentration of TPH-diesel (610 mg/kg) in sediment collected from the bottom of IR21CB1 exceeded the Tier 2 screening level for TPH-diesel of 500 mg/kg (CH2M HILL 2009h). In addition, lead was detected in the sample collected from this CB at a concentration (8,400 mg/kg) above the USEPA industrial RSL of 800 mg/kg (USEPA 2009b). Concentrations of PCBs and TPH-motor-oil in the sediment sample collected from IR21CB1 did not exceed their respective screening levels. As discussed in Section 2.2.1, based on the elevated detections of TPH-diesel and lead in sediment at IR21CB1, step-out sampling along the storm sewer pipelines was performed.

Four total composite samples were collected from the accumulated sediments in the bottom of IR21CB2, IR21CB3, IR21CB4, and IR21MH2. Because PCBs did not exceed screening levels in the sediment sample collected from IR21CB1, these sediment samples were analyzed for TPH-diesel, TPH-motor-oil, and lead. Concentrations of lead were below the USEPA industrial RSL in all four samples. TPH-diesel was detected (780J [J=estimated] mg/kg) in the sediment sample collected from upgradient IR21CB2, which exceeded the Tier 2 screening level of 500 mg/kg for TPH-diesel (CH2M HILL 2009h). TPH-motor-oil was detected (3,500 mg/kg and 3,000 mg/kg) in sediment samples collected from upgradient IR21CB2 and IR21CB3, respectively, which exceeded the Tier 2 screening level for TPH-motor-oil of 500 mg/kg (CH2M HILL 2009h). Concentrations of TPH-diesel, TPH-motor-oil, and lead were not detected above their respective screening levels in the downgradient IR21CB4.

Because one or more known COCs were detected in sediment above their respective screening levels at the storm sewer CB locations near the IR21/Buildings 386/388/390 Area, cleaning activities were recommended during an agency meeting on April 28, 2009 (CH2M HILL 2009i). CH2M HILL recommended that sediment and water be removed from the impacted CBs, followed by flushing/rinsing of the pipeline segments that connect these structures. DTSC and Water Board verbally approved the cleaning approach during this agency meeting. Additionally, DTSC agreed to the cleaning approach in an email dated December 9, 2009 (DTSC 2009c). Section 3.0 discusses the cleaning activities performed at the storm sewer system near the IR21/Buildings 386/388/390 Area.

2.3 PCB Site Building 678 AL#04

2.3.1 Sampling Activities

On February 11, 2008, CH2M HILL conducted site maintenance activities at PCB Site Building 678 AL#04 to remove sediment from CB B678GB1 (Figure 1-4), as discussed in the Site Characterization and Cleanup Action Summary Report for Polychlorinated Biphenyl Site Building 678 AL#04, Investigation Area C2, Lennar Mare Island, Vallejo, California (CH2M pending(b)). The sediment and water were removed from B678GB1; however, a confirmation sample was not collected following the removal activities. Because PCBs were detected in a sediment sample (B678AL04-0809) collected from the bottom of B678GB1 in June 2004, a confirmation concrete chip sample (B678GB1CS0101) was collected and analyzed for PCBs using USEPA Method 8082 as part of the March 2009 storm sewer system sampling activities. During implementation of the March 2009 storm sewer system sampling

activities, sediment and water were removed from this CB to proceed with the concrete chip sampling. A confirmation concrete chip sample (B678GB1CS0101) was collected from the bottom of B678GB1 at 3 feet bgs and was submitted for analysis of PCBs using USEPA Method 8082.

2.3.2 Screening-level Criteria

The analytical results for the concrete chip sample were compared to the USEPA industrial RSL of 0.74 mg/kg for concrete media (USEPA 2009b).

2.3.3 Results

The total PCB concentration (only Aroclor-1260 detected) (0.033 mg/kg) in the concrete chip sample was less than the USEPA industrial RSL of 0.74 mg/kg for PCBs (USEPA 2009b). Therefore, no additional investigation/remedial activities are required for the storm sewer system located near PCB Site Building 678 AL#04. The sample results and request for no additional investigation/remedial activities for the storm sewer system near PCB Site Building 678 AL#01 were presented to DTSC and the Water Board during an agency meeting on April 28, 2009 (CH2M HILL 2009i). DTSC and Water Board verbally approved no additional investigation/remedial activities are required for the storm sewer system near PCB Site Building 678 AL#04 during an agency meeting on April 28, 2009. Additionally, DTSC approved that no additional investigation/remedial activities are required for the storm sewer system near PCB Site Building 678 AL#04 in an email on December 9, 2009 (DTSC 2009c).

2.4 PCB Site Building 830 UL#01

2.4.1 Sampling Activities

Based on the outdoor location of PCB Site Building 830 UL#01 and the historical detections of PCBs in transformer oil and concrete samples, CB B830CB1, located south of Building 830, was investigated, as shown in Figure 1-5. During the March 2009 sampling activities, sediment, soil, and water were removed from B830CB1 to facilitate collection of a concrete chip sample. Following the removal of sediment, soil, and water, a concrete chip sample (B830CB1CS0101) was collected from the accumulated sediments in the bottom of B830CB1 at 3.5 feet bgs. The sample was analyzed for PCBs using USEPA Method 8082.

2.4.2 Screening-level Criteria

The analytical results for the concrete chip sample were compared to the USEPA industrial RSL of 0.74 mg/kg (USEPA 2009b).

2.4.3 Results

Concentrations of total PCBs (0.055J mg/kg) in the concrete chip sample did not exceed the USEPA industrial RSL of 0.74 mg/kg (USEPA 2009b); therefore, no additional investigation/remedial activities are required for the storm sewer system near PCB Site Building 830 UL#01. The sample results and request for no additional investigation/remedial activities for the storm sewer system near PCB Site Building 830 UL#01 were

presented to DTSC and the Water Board during an agency meeting on April 28, 2009 (CH2M HILL 2009i). DTSC and Water Board verbally approved no additional investigation/remedial activities are required for the storm sewer system near PCB Site Building 830 UL#01 during the agency meeting. Additionally, DTSC approved no additional investigation/remedial activities are required for the storm sewer system near PCB Site Building 830 UL#01 in an email on December 9, 2009 (DTSC 2009c).

3.0 IR21/Buildings 386/388/390 Area Cleaning Activities

As discussed in Section 2.2, lead, TPH-motor-oil, and TPH-diesel were detected in sediment samples collected from the bottom of three CBs (IR21CB1, IR21CB2, IR21CB3) at the storm sewer system near the IR21/Buildings 386/388/390 Area at levels above their respective screening levels, as shown in Figure 1-3. To address these detections in sediment above screening levels, the storm sewer system cleaning activities included the removal of sediment and water from the impacted storm sewer CBs followed by flushing/rinsing the pipeline segments (approximately 600 lineal feet) that connect these structures. CH2M HILL proposed this approach to DTSC and Water Board during an agency meeting on April 28, 2009 (CH2M HILL 2009i). DTSC agreed to this approach in an email correspondence dated December 9, 2009 (DTSC 2009c).

3.1 Cleaning Activities and Cleanup Objectives

In May 2009 and March 2010, as part of the storm sewer system cleaning near the IR21/Buildings 386/388/390 Area, CH2M HILL:

- Conducted closed-circuit television (CCTV) video inspection of the storm sewer pipeline segments prior to cleaning activities.
- Conducted a site reconnaissance of the storm sewer CBs/MHs and pipelines.
- Removed sediment/water from three CBs (IR21CB1, IR21CB2 and IR21CB3) where lead, TPH-motor-oil, and TPH-diesel were detected above screening levels followed by pressure washing these CBs. Sediment and water were removed from four MHs (IR21MH2, IR21MH3, IR21MH4, and IR21MH5), followed by pressure washing of these MHs to facilitate cleaning activities.
- Flushed/rinsed three storm sewer pipeline segments (between MH2 and MH4, MH5 and CB1, and CB1 and CB2) connecting the CB/MH structures.
- Collected a confirmation rinsate samples from the nearest CB or MH connected to each
 of the three flushed pipeline segments.
- Analyzed the three rinsate water samples for lead, TPH-motor-oil, and TPH-diesel and compared the analytical results to Tier 2 screening levels for groundwater at sites located greater than 300 ft from a sensitive receptor (CH2M HILL 2009h).
- Conducted CCTV video inspection of the flushed/rinsed storm sewer pipeline segments following the completion of cleaning activities.
- Performed a pipeline tracer video inspection at IR21CB3.
- Disposed waste sediment, solids and water generated from the storm sewer system cleaning activities in accordance with appropriate state and federal requirements.

3.2 Subcontractors

The March 2010 storm sewer system cleaning activities included the following subcontractors:

- Innovative Construction Solutions, Norcal (ICS): Supervised the storm sewer system cleaning activities.
- **Subtronic Corporation:** Conducted CCTV video inspections of the pipeline segments and a pipeline tracer video inspection at storm sewer IR21CB3.
- KM Industrial: Conducted vacuum removal of sediment/water from the storm sewer CBs/MHs, pressure washing of the CBs/MHs, and flushing/rinsing of the storm sewer pipeline segments.

3.3 Summary of Cleaning Activities

Between March 22 and 31, 2010, CH2M HILL performed storm sewer system cleaning activities near the IR21/Building 386/388/390 Area. This section summarizes the cleanup activities.

3.3.1 Pre-cleaning Activities – CCTV Video Inspection

Prior to the cleaning activities in March 2010, Subtronic Corporation performed a CCTV video inspection on May 19, 2009. The CCTV video inspection was conducted to evaluate the storm sewer pipeline conditions prior to performing the flushing/rinsing activities for these pipelines. During the pre-cleaning CCTV video inspection, the storm sewer pipelines were observed to contain cracks, joint offsets, pipe diameter changes, and lateral pipeline connections. Additionally, it was discovered that the bottom of the storm sewer pipeline between MH4 and MH5 was missing, as shown in Figure 3-1. Due to the amount of debris (e.g., rocks, mud, wood) in the storm sewer pipelines, the CCTV inspection could not be performed along the entire length (approximately 600 lineal feet) of the storm sewer pipelines proposed for cleaning. Specifically, the storm sewer pipeline exiting IR21CB3 (Figures 3-1) could not be inspected because it was full of sediment and water; the storm sewer pipeline segment between IR21CB1 and IR21CB2 could not be fully inspected because it was full of mud; and the storm sewer pipeline segment between IR21MH4 and IR21MH5 could not be inspected beyond the broken segment.

CH2M HILL reviewed the CCTV video inspection report with the VSFCD on October 6, 2009. The proposed cleaning activities were submitted to the VSFCD in a letter dated November 13, 2009 (CH2M HILL 2009j). The VSFCD responded to this letter in an email on December 10, 2009 (VSFCD 2009), which stated that the VSFCD agreed to the proposed cleaning activities and understands that the storm sewer pipelines are in poor condition. In this email, the VSFCD requested that CCTV video inspection be performed following completion of the storm sewer system cleaning activities to document the condition of the pipelines.

3.3.2 Pre-cleaning Activities – Şite Reconnaissance

ICS mobilized to the site on March 22, 2010, and a site reconnaissance was conducted with CH2M HILL to facilitate the planned storm sewer system cleaning activities. The following observations were made during the site reconnaissance:

- Several CBs/MHs shown on storm sewer Navy Quad maps for the site could not be located. The storm sewer Navy Quad maps were used to create the storm sewer configuration at the IR21/Buildings 386/388/390 Area shown in Figures 1-3 and 3-1 through 3-3. The CBs and MHs that appear on storm sewer Navy Quad maps that were not observed at the site are shown in these figures. A description of stormwater drainage through the storm sewer system near the IR21/Buildings 386/388/390 Area, based on current understanding of site conditions, is discussed in Section 3.3.3.
- A pipeline connection between IR21CB3 and IR21MH2, shown on storm sewer Navy Quad maps for the site, was found to be disconnected. A pipeline exiting IR21CB3 was observed; however, an inlet pipeline to IR21MH2 was not observed. A pipeline tracer video inspection was performed by Subtronic Corporation on March 26, 2010 to evaluate where the outlet pipeline in IR21CB3 leads, as described in Section 3.3.6. Additionally, a pipeline connection between IR21CB3 and the CB immediately upgradient of IR21CB3 on the west side of Building 386 (Figure 3-1) was not observed. The storm sewer Navy Quad maps for the site show a connection between these two CBs; however, an inlet pipeline in IR21CB3 from the upgradient direction was not observed during the site reconnaissance. Figure 3-1 show the observed configuration of these pipelines based on field observations.
- Lateral pipeline connections were observed in IR21MH3, IR21MH4, and IR21MH5. These lateral pipelines were also noted during the CCTV video inspections (discussed in Section 3.3.1 and 3.3.7). Figure 3-1 show the observed configuration of these pipelines based on field observations.
- IR21CB2 has one outlet pipeline that connects to IR21CB1. There is no inlet pipeline in IR21CB2, as shown in Figure 3-1.
- Two 1-inch-diameter electrical conduit pipes were found passing through the top of IR21MH1, as shown in Figure 3-1. Because they were passing through the top of the MH, cleaning activities could proceed at the bottom of IR21MH1 without removing the electrical conduit pipes.

3.3.3 Stormwater Drainage around the IR21/Buildings 386/388/390 Area

This section discusses stormwater drainage through the storm sewer system near the IR21/Buildings 386/388/390 Area and is based on current understanding of site conditions. Stormwater that does not infiltrate into the subsurface enters one of the CBs or MHs surrounding the building. The stormwater is then carried downgradient through the storm sewer pipelines located along the north, south, and east sides of the combined Buildings 386/388/390, under Railroad Avenue in the direction of Mare Island Strait, as depicted in Figure 3-1.

As mentioned in Section 3.3.2, stormwater collected in IR21CB2 flows downgradient to IR21CB1, then downgradient across Railroad Avenue in the direction of Mare Island Strait. Additionally, stormwater entering IR21CB3 appears to be isolated due to an obstruction. As mentioned in Section 2.2.1, the storm sewer pipeline segments between IR21MH1 and IR21CB1 and between IR21CB1 and IR21CB2 were investigated because these pipelines appear to form a junction at the southeast corner of the combined Buildings 386/388/390 that appears to capture the majority of the stormwater flow around Buildings 386/388/390. The apparent direction of stormwater flow in the storm sewer pipelines, based on field observations, is shown in Figure 3-1.

3.3.4 Storm Sewer System Cleaning Activities

KM Industrial mobilized to the site on March 23, 2009 to perform the cleaning activities. The cleaning activities included vacuum removal of accumulated sediment and water from three CBs (IR21CB1, IR21CB2, and IR21CB3) and four MHs (IR21MH2, IR21MH3, IR21MH4, and IR21MH5) prior to flushing/rinsing the pipeline segments. Following the removal of sediments and water, the CBs/MHs were pressure washed. Storm sewer pipeline segments between IR21CB1 and IR21CB2, IR21CB1 and IR21MH5, and IR21MH2 and IR21MH4, consisting of approximately 600 lineal feet of pipeline, were flushed/rinsed until few or no solids were visible in the rinse water. Figure 3-1 shows the location of the storm sewer CBs/MHs and pipeline segments.

The storm sewer pipeline segments were flushed/rinsed using a combination of a vacuum and high-pressure washer truck. The pressure washer truck supplied water to a nozzle that propelled itself through the lateral sewer. Upon retrieving the nozzle under water pressure, accumulated material in the pipeline was forced loose and backflushed to the CB or MH where it was vacuumed and removed. Pneumatic plugs were used to plug the lateral pipeline connections on the storm sewer pipeline so that water would not be flushed into other pipeline segments. Additionally, pneumatic plugs were used to plug IR21MH4 and IR21MH5 so that water would not be flushed onto underlying soils located beneath the broken pipeline segment between IR21MH4 and IR21MH5.

Approximately 2-3 tons of sediment and waste solids were removed and disposed of offsite at Clean Harbors disposal facility. In addition, approximately 7,500 gallons of waste water were collected as part of the cleaning activities. The waste sediments and water were disposed of as discussed in Section 3.6 of this report.

3.3.5 Sample Collection

Prior to cleaning activities, ICS collected a water sample from the vacuum and high-pressure washer truck and analyzed it for lead, TPH-diesel, and TPH-motor-oil to determine their concentrations in the source water. The concentrations of lead and TPH-diesel in this water sample were 20 $\mu g/L$ and 360 $\mu g/L$, respectively. TPH-motor-oil was not detected above the laboratory reporting limit (100 $\mu g/L$) in the source water sample. The laboratory analytical report for the source water sample is included in Appendix A.

Once few or no solids were observed in the rinse water in each of the three flushed pipeline segments, grab rinsate water samples from the pipeline segments between IR21CB1 and IR21CB2 (sample IR21SSCB1CB2 from IR21CB2), IR21CB1 and IR21MH5 (sample

IR21SSCB1MH5 from IR21MH5), and IR21 MH2 and IR21MH4 (sample IR21SSMH4MH2 from IR21MH4) were collected from the nearest CB or MH (shown in Figure 3-1) and were submitted for laboratory analysis of lead using USEPA Method 6010B and for analysis of TPH-diesel and TPH-motor-oil using USEPA Method 8015B. The results of the rinsate water samples are discussed in Section 3.4.

3.3.6 Pipeline Tracer Video Inspection at CB3

Cleaning activities concluded on March 26, 2010, and KM Industrial demobilized from the site. On March 26, 2010, Subtronic Corporation conducted a video pipeline tracer inspection at IR21CB3 located on the west side of Building 386. The camera was inserted into the 4-inch-diameter pipeline exiting the southern portion of IR21CB3 to determine where the pipe leads. The camera was underwater beginning at approximately 2 feet, and an obstruction was encountered at approximately 40 feet into the pipeline, shown in Figure 3-1. The camera was located with a handheld pipe locator at ground surface, which detected the camera at the obstruction. Based on the handheld pipe locator, the camera was detected at a location approximately 30 feet east of the manhole (IR21MH2) and adjacent to the 8-inch polyvinyl chloride storm sewer pipeline segment between IR21MH2 and IR21CB1, shown in Figure 3-1. This observed configuration is in disagreement with the storm sewer Navy Quad maps that show a storm sewer pipeline connecting IR21CB3 and IR21MH2. Additionally, a lateral pipeline exiting the north portion of MH3 was observed. This pipeline appears to lead into Building 386; however, the pipe was also fully obstructed and could not be located or videoed. The observed pipeline configuration at IR21CB3, IR21MH2, and IR21MH3 is shown in Figure 3-1.

3.3.7 Post-cleaning CCTV Video Inspection

As discussed above, a CCTV video inspection was performed after the completion of the storm sewer system cleaning activities at the request of the VSFCD (VSFCD 2009) to document the conditions of the pipelines. The post-cleaning CCTV video inspection was conducted on March 31, 2010 by Subtronic Corporation. The VSFCD was present during the post-cleaning CCTV video inspection to observe the condition of the storm sewer pipelines. Based on the observations recorded during the pre- and post-cleaning CCTV video inspections, the storm sewer system cleaning activities did not impact the existing integrity of the pipelines. In a letter to the VSFCD dated June 28, 2010 (CH2M HILL 2010), CH2M HILL documented the cleaning activities at the storm sewer pipelines near the IR21/Buildings 386/388/390.

3.4 Results of Cleaning Activities

Table 3-1 provides the analytical results for the rinsate water samples compared to their respective Tier 2 screening levels for groundwater at sites located greater than 300 feet from a sensitive receptor (e.g. Mare Island Strait) (CH2M HILL 2009h). Figure 3-1 also shows these results along with the approximate location of the sample collection. As shown in Table 3-1 and Figure 3-1, the concentrations of lead, TPH-diesel, and TPH-motor-oil in each of the rinsate water samples were below their applicable Tier 2 screening levels.

TABLE 3-1
Analytical Results for Rinsate Water Samples Following Storm Sewer System Cleaning Activities near the IR21/Buildings 386/388/390 Area

Site Summary Report for the Storm Sewer System near IR19, IR21/Buildings 386/388/390 Area, PCB Site Building 678 AL#04, and PCB Site Building 830 UL#01 in Investigation Area C2, Lennar Mare Island Vallejo, California

Parameter	Screening Criteria ^a (μg/L)	Pipeline Segment CB1-CB2 IR21SSCB1CB2 (µg/L)	Pipeline Segment CB1-MH5 IR21SSCB1MH5 (μg/L)	Pipeline Segment MH4-MH2 IR21SSMH4MH2 (μg/L)
TPH-diesel	5,000	150J	590J	360J
TPH-motor-oil	5,000	240J	540	860
Lead	50,000	3.7	450	1,000

^aTier 2 Screening Level (for sites >300 ft from sensitive receptors).

3.5 Evaluation of Soil and Groundwater Along Broken Pipeline Segment (MH4 to MH5)

As described in Section 3.3.1, the bottom of the storm sewer pipeline between IR21MH4 and IR21MH5 appeared to be missing during the CCTV video inspection on May 19, 2009 and March 31, 2009. An evaluation of existing sample data within a 25-foot radius of this broken pipeline segment and the nearest downgradient groundwater monitoring wells was performed to assess potential impacts to underlying soil and groundwater due to releases, if any, from this storm sewer pipeline segment. Figures 3-2 and 3-3 show the existing soil and groundwater data for TPH-diesel, TPH-motor-oil, lead, and PCBs on or near this broken pipeline segment. Concentrations of TPH-diesel and TPH-motor-oil in soil samples were compared to Tier 2 screening levels (CH2M HILL 2009h), and concentrations of lead and PCBs were compared to the USEPA industrial RSLs (USEPA 2009b). Concentrations of TPH-diesel, TPH-motor-oil, lead, and PCBs in groundwater samples were compared to Tier 2 screening levels (CH2M HILL 2009h).

As shown in Figure 3-2, one soil sample (B382GB0100 at 5.5 feet bgs) located approximately 5 to 10 feet from the broken pipeline segment contains concentrations of TPH-diesel (7,300 mg/kg) and TPH-motor oil (8,200 mg/kg) that exceed the Tier 2 screening levels. The remaining soil samples collected from locations on or adjacent to the broken pipeline segment are below Tier 2 screening levels. Based on the boring log for soil sample B382GB0100 (CH2M HILL 2009g), three borings were hand-augered at this location. Oil was observed at 5.5 feet bgs within cracks and laminations in the surrounding soil but was not in the soil matrix. These observations are consistent with the conceptual site model that was presented in the *Final Feasibility Study/Removal Action Work Plan for IR21 and the Buildings 386/388/390 Area, Investigation Area C2, Lennar Mare Island, Vallejo, California* (CH2M HILL 2009g). Site conditions suggest the TPH found in this soil sample was not released from the storm sewer pipeline. The TPH-motor-oil concentration (5,200Y [Y=fuel pattern (TPH only)] mg/kg) in the soil sample collected from downgradient boring B382GB002 exceeds the Tier 2 screening level. Soil sample locations B382GB0100 and B382GB002 will be addressed by the TPH Notification that will be included as part of the

site-specific LUC for the IR21/Building 386/388/390 Area. Concentrations of TPH-diesel and TPH-motor-oil in soil samples collected from the other soil and groundwater locations near the storm sewer pipeline do not exceed Tier 2 screening levels. One grab groundwater sample from boring B382GB001 contained concentrations of TPH-diesel (54,000,000Y μ g/L) and TPH-motor-oil (150,000,000Y μ g/L) that exceed the Tier 2 screening levels. However, TPH-diesel and TPH-motor-oil did not exceed Tier 2 screening levels in downgradient monitoring wells IR21MW0106 and B388W01, which were sampled intermittently between 1999 and 2007 and quarterly between February 2007 and April 2009. Therefore, TPH impacts to groundwater appear to be limited to the area around these two borings. These observations are consistent with the IR21/Buildings 386/388/390 Area, as discussed in the *Final Feasibility Study/Removal Action Work Plan for IR21 and the Buildings 386/388/390 Area, Investigation Area C2, Lennar Mare Island, Vallejo, California* (CH2M HILL 2009g).


As shown in Figure 3-3, concentrations of Aroclor-1254 (5J mg/kg) in a soil sample collected from sample location B390GB007 at 3 feet bgs exceeds the USEPA industrial RSL of 0.74 mg/kg (USEPA 2009b). Concentrations of lead in soil and groundwater and PCBs in groundwater in the remaining samples did not exceed screening levels. Because the soil sample B390GB016 is located approximately 25 feet north of the storm sewer pipeline, it does appear that PCBs in this sample location are not related to a release from the broken storm sewer pipeline segment between MH4 to MH5, if any. Based on the results described above, no further action is proposed for soil and groundwater at the storm sewer system near the IR21/Buildings 386/388/390 Area. A TPH notification will be included in the IA C2 Commercial/Industrial LUC, which will identify soil sample locations where concentrations of TPH-related constituents have been detected at concentrations above the odor/nuisance screening levels.


3.6 Waste Management


Sediments and solids removed from the CB/MH structures were containerized for disposal in accordance with appropriate state and federal requirements.

The accumulated water (approximately 7,500 gallons) removed from the CBs/MHs and the rinsate water generated from the flushing/rinsing of the pipeline segments were containerized in a fractionalization tanks and were analyzed for VSFCD sanitary sewer discharge criteria. The analytical results of these samples met the VSFCD discharge criteria and a permit to discharge the water into the sanitary sewer was approved by VSFCD on April 7, 2010. A copy of the rinsate wastewater analytical results and the permit are included in Appendix C.

The accumulated sediment and solids removed from the CBs/MHs and pipeline segments (approximately 2-3 tons) were contained in a roll-off bin and were analyzed for Clean Harbors disposal facility criteria. A copy of the waste profile and disposal manifest is included in Appendix D.







4.0 Conclusions and Criteria for Obtaining Site Closure

4.1 Conclusions

The storm sewer system sampling activities was initiated in March 2009 and addressed storm sewer CBs and/or MHs located downgradient of the following sites in IA C2:

- IR19
- IR21/Buildings 386/388/390 Area
- PCB Site Building 678 AL#04
- PCB Site Building 830 UL#01

The storm sewer system investigation consisted of an initial round of sediment or concrete chip sampling and analysis for CBs and MHs immediately downgradient of these four sites. If sediment was present, a composite sediment sample was collected from the accumulated sediments in the bottom of the CB or MH and was submitted for analysis of the known COCs encountered at the immediately upgradient site. A concrete chip sample was collected from the bottom of the CBs at sites impacted by PCBs only. Because the analytical results of the first round of sampling exceeded screening levels, step-out sampling to CBs/MHs located along the storm sewer pipeline was performed to evaluate the concentrations of COCs downgradient in the pipeline at IR21/Buildings 386/388/390 Area.

The analytical results for sediment and concrete chip samples collected from storm sewer CBs/MHs near IR19, PCB Site Building 678 AL#04, and PCB Site Building 830 UL#01 were below their respective screening levels. DTSC and Water Board verbally approved no additional investigation/remedial activities for the storm sewer system near these sites during an agency meeting on April 28, 2009. DTSC provided written approval in an email dated December 9, 2009 (DTSC 2009c).


CH2M HILL conducted storm sewer system cleaning activities near the IR21/Buildings 386/388/390 Area in March 2010. The cleaning activities consisted of removing impacted sediment and water from storm sewer CBs and MHs, followed by flushing/rinsing the pipeline segments that connect these structures. Following the completion of these cleaning activities, rinsate water samples were collected from the flushed/rinsed pipeline segments and were analyzed for lead, TPH-diesel, and TPH-motor-oil. The concentrations of these constituents in the rinsate samples were all below their applicable Tier 2 screening levels for groundwater at commercial/industrial sites. Additionally, soil and groundwater samples collected from locations above or near the broken storm sewer pipeline segment (MH4 to MH5) (shown in Figures 3-2 and 3-3) were analyzed for TPH-diesel, TPH-motor-oil, PCBs, and lead. On the basis of these results, there is no evidence of impacts from releases, if any, from the storm sewer; therefore, additional investigation/remedial activities are not proposed for the IR21/Buildings 386/388/390 Area.


4.2 Criteria for No Further Action

Analytical results in sediment, concrete chip and rinsate water samples collected from storm sewer CBs/MHs or pipelines near IR19, IR21/Buildings 386/388/390 Area, PCB Site Building 678 AL#04, and PCB Site Building 830 UL#01 meet their applicable screening criteria. Therefore, CH2M HILL requests DTSC concurrence that additional investigation/remedial activities for the storm sewer system near these sites in IA C2 are not necessary.

5.0 References

California Environmental Protection Agency, Department of Toxic Substances Control (DTSC). 2003a. Letter. "Lennar Mare Island, Final Site ID Technical Memorandum for Investigation Area B, dated July 16, 2002." January 15.
. 2003b. Letter. "Lennar Mare Island, Final Site ID Technical Memorandum for Investigation Area C1, Dated May 2002." February 20.
2003c. Letter. "Lennar Mare Island, Final Site ID Technical Memorandum for Investigation Area C2, Revised March 14, 2003." May 20.
. 2003d. Letter. "Lennar Mare Island, Final Site ID Technical Memorandum for Investigation Area C3, Dated May 24, 2002." January 17.
2003e. Letter. Lennar Mare Island, Final Site ID Technical Memorandum for Investigation Area D1, Dated April 17, 2003". November 6.
2003f. Letter. "Lennar Mare Island, Final Site ID Technical Memorandum for Investigation Area H2, Dated May 9, 2002." January 10.
2007a. Letter. "Lennar Mare Island, Draft Site Characterization and Cleanup Action Report for PCB Site at Building 516 and 516A in Investigation Area C3, dated May 17, 2007." July 18.
2007b. Letter. "Lennar Mare Island, Draft Removal Action Work Plan for IR21, Investigation Area C2, May 2006." January 4.
2008. Letter. "Lennar Mare Island, Site Characterization and Cleanup Summary Report for PCB Site At Building 535 AL#01 and AL#02 in Investigation Area B.2, Dated February 13, 2008." March 25.
. 2009a. Letter. "Lennar Mare Island Response To DTSC Comments for Storm Sewer System at PCB Site Building 516 AL#01, Investigation Area C3, Dated February 26, 2009." April 22.
2009b. Telephone Conversation between Henry Chui/DTSC and Jennifer Low, CH2M HILL. Discussion of Historical Detection of PCBs in Sediment and Water from Manhole D1_M13. January 14.
2009c. Email from Henry Chui/DTSC to Paula Bolio/CH2M HILL. "RE: Storm Sewer SAP Approach." December 9.
California Regional Water Quality Control Board, San Francisco Bay Region (Water Board). 2003a. Letter. "RWQCB Comments on the Final Investigation Area C2 Site Identification Technical Memorandum, Mare Island, Solano County (October 15, 2002)." February 13.





- Lennar Mare Island, the City of Vallejo, and the State of California, Environmental Protection Agency Department of Toxic Substances Control. 2001. Consent Agreement between Lennar Mare Island, the City of Vallejo, and the State of California, California Environmental Protection Agency Department of Toxic Substances Control. April 16.
- United States Environmental Protection Agency (USEPA). 2009a. Letter. "Site Characterization and Cleanup Action Summary Reports for Polychlorinated Biphenyl Sites 516 and 516A in Investigation Area C3, Eastern Early Transfer Parcel, mare Island, Vallejo, California, and Reports dated May 17, 2007, October 3, 2007, and February 26, 2009." August 31.
- ______. 2009b. Regional Screening Levels for Chemical Contaminants at Superfund Sites.

 December 5.
- Vallejo Sanitation and Flood Control District (VSFCD). 2009. Email from Mike Monahan/VSFCD to Mike Godwin/CH2M HILL. "Re: SD Cleaning near B382, 386, 388, 390." December 10.

Appendix A
Analytical Results for Sediment, Concrete Chip,
and/or Rinsate Water Samples Collected from
the Storm Sewer System near IR19,
IR21/Buildings 386/388/390 Area,
PCB Site Building 678 AL#04, and
PCB Site Building 830 UL#01

2009 Analytical Results for Sediment, Concrete Chip and/or Rinsate Water Samples collected from the Storm Sewer System near IR19, IR21/Buildings 386/388/390 Area, PCB Site Building 678 AL#04 and PCB Site Building 830 UL#01

Site Summary Report for the Storm Sewer System near IR19, IR21/Buildings 386/388/390 Area, PCB Site Building 678 AL#04 and PCB Site Building 830 UL#01 in Investigation Area C2, Lennar Mare Island, Vallejo, California

Location of Sample	Sample Identifier	QA/QC Type	Value mg/kg	Flag	Date and Time of Sample	Beginning	e Depths g _ Ending t bgs)	Removed?	Type of Sample	Source of Measurement
PCB Compounds						٠		•		
Analyte AROCLOR-1016	CAS Number 12674-11-2							-		
B678GB1CS0101 B830CB1CS0101 AROCLOR-1221	B678GB1CS0101-C3 B830CB1CS0101-C3.5 11104-28-2	ORIG ORIG	2.1E-03 2.1E-03	U U	03/12/09 14:40 03/13/09 14:25	3.0 3.5	3.5 4.0	N N	Concrete Chip Concrete Chip	Laboratory Laboratory
B678GB1CS0101 B830CB1CS0101 AROCLOR-1232	B678GB1CS0101-C3 B830CB1CS0101-C3.5 11141-16-5	ORIG ORIG	4.2E-03 4.3E-03	υ U	03/12/09 14:40 03/13/09 14:25	3.0 3.5	3.5 4.0	N	Concrete Chip Concrete Chip	Laboratory Laboratory
B678GB1CS0101 B830CB1CS0101 AROCLOR-1242	B678GB1CS0101-C3 B830CB1CS0101-C3.5 53469-21-9	ORIG ORIG	2.7E-03 2.8E-03	U U	03/12/09 14:40 03/13/09 14:25	3.0 3.5	3.5 4.0	N N	Concrete Chip Concrete Chip	Laboratory Laboratory
B678GB1CS0101 B830CB1CS0101 AROCLOR-1248	B678GB1CS0101-C3 B830CB1CS0101-C3.5 12672-29-6	ORIG ORIG	8.3E-04 8.5E-04	U U	03/12/09 14:40 03/13/09 14:25	3.0 3.5	3.5 4.0	N	Concrete Chip Concrete Chip	Laboratory Laboratory
B678GB1CS0101 B830CB1CS0101 AROCLOR-1254	B678GB1CS0101-C3 B830CB1CS0101-C3.5 11097-69-1	ORIG ORIG	8.7E-04 8.9E-04	U	03/12/09 14:40 03/13/09 14:25	3.0 3.5	3.5 4.0	N N	Concrete Chip Concrete Chip	Laboratory • Laboratory
B678GB1CS0101 B830CB1CS0101 AROCLOR-1260	B678GB1CS0101-C3 B830CB1CS0101-C3.5 11096-82-5	ORIG ORIG	2.1E-03 2.1E-03	U U	03/12/09 14:40 03/13/09 14:25	3.0 3.5	3.5 4.0	N N	Concrete Chip Concrete Chip	Laboratory Laboratory
B678GB1CS0101 B830CB1CS0101 AROCLOR-1262	B678GB1CS0101-C3 B830CB1CS0101-C3.5 37324-23-5	ORIG ORIG	3.3E-02 5.5E-02	= J	03/12/09 14:40 03/13/09 14:25	3.0 3.5	3.5 4.0	N N	Concrete Chip Concrete Chip	Laboratory Laboratory
B678GB1CS0101 B830CB1CS0101	B678GB1CS0101-C3 B830CB1CS0101-C3.5	ORIG ORIG	1.3E-02 1.3E-02	U U	03/12/09 14:40 03/13/09 14:25	3.0 3.5	3.5 4.0	N	Concrete Chip Concrete Chip	Laboratory Laboratory
NOTE: Rinsate samples collected from neares	t catch basin or manhole.					^a FLAG = J U UJ	Detected Resul Estimated Dete Nondetect Resul Estimated Nonde	cted Result		

· NOTE:

2009 Analytical Results for Sediment, Concrete Chip and/or Rinsate Water Samples collected from the Storm Sewer System near IR19, IR21/Buildings 386/388/390 Area, PCB Site Building 678 AL#04 and PCB Site Building 830 UL#01

Site Summary Report for the Storm Sewer System near IR19, IR21/Buildings 386/388/390 Area, PCB Site Building 678 AL#04 and PCB Site Building 830 UL#01 in Investigation Area C2, Lennar Mare Island, Vallejo, California

Location of Sample PCB Compounds	Sample Identifier	QA/QC Type	Value mg/kg	Flag ^{a `}	Date and Time of Sample	Sample I Beginning (feet b	Ending	Removed?	Type of Sample	Source of Measurement [←]
Analyte AROCLOR-1268	CAS Number 11100-14-4			-						
B678GB1CS0101	B678GB1CS0101-C3	ORIG	1.3E-02	U	03/12/09 14:40	3.0	3.5	N	Concrete Chip	Laboratory
B830CB1CS0101 TOTAL PCB CALCULATION	B830CB1CS0101-C3.5 TOTAL PCBS	ORIG	1.3E-02	U	03/13/09 14:25	3.5	4.0	N ·	Concrete Chip	Laboratory
B678GB1CS0101	B678GB1CS0101-C3	ORIG	3.3E-02	=	03/12/09 14:40	3.0	3.5	N	Concrete Chip	Laboratory
B830CB1CS0101	B830CB1CS0101-C3.5	ORIG	5.5E-02	J	03/13/09 14:25	3.5	4,0	N	Concrete Chip	Laboratory

a FLAGS

Rinsate samples collected from nearest catch basin or manhole.

Detected Result

Estimated Detected Result

U Nondetect Result

UJ Estimated Nondetect Result

2009 Analytical Results for Sediment, Concrete Chip and/or Rinsate Water Samples collected from the Storm Sewer System near IR19, IR21/Buildings 386/388/390 Area, PCB Site Building 678 AL#04 and PCB Site Building 830 UL#01

Site Summary Report for the Storm Sewer System near IR19, IR21/Buildings 386/388/390 Area, PCB Site Building 678 AL#04 and PCB Site Building 830 UL#01 in Investigation Area C2, Lennar Mare Island, Vallejo, California

Location of Sample	Sample Identifier	QA/QC Type	Value mg/kg	Flag	Date and Time of Sample	Beginning	e Depths g Ending t bgs)	Removed?	Type of Sample	Source of Measurement
etroleum Hydrocarbon Comp	ounds		.55						·)
Analyte DIESEL	CAS Number DRO									
IR21CB1SD0101	IR21CB1SD0101-S6	ORIG	6.1E+02	=	03/10/09 10:30	6.0	6.5	Y	Sediment Sample	Laboratory
. IR21CB2SD0101	IR21CB2SD0101-S3	ORIG	7.8E+02	J	03/25/09 15:40	3.0	3.5	Υ	Sediment Sample	Laboratory
IR21CB3SD0101	IR21CB3SD0101-S3.5	ORIG	4.4E+02	J	03/25/09 14:00	3.0	3.5	Υ	Sediment Sample	Laboratory
IR21CB4SD0101	IR21CB4SD0101-SD6	ORIG	4.1E+02	J	05/01/09 09:00	6.0	6.5	Υ	Sediment Sample	Laboratory
IR21MH2SD0101	IR21MH2SD0101-S4	ORIG	1.7E+02	J	03/25/09 13:50	3.0	3.5	Υ	Sediment Sample	Laboratory
MOTOR OIL	MRO									
IR21CB1SD0101	IR21CB1SD0101-S6	ORIG	1.4E+03	=	03/10/09 10:30	6.0	6.5	Υ	Sediment Sample	Laboratory
IR21CB2SD0101	IR21CB2SD0101-S3	ORIG	3,5E+03.	=	03/25/09 15:40	3.0	3.5	Υ	Sediment Sample	Laboratory
IR21CB3SD0101	IR21CB3SD0101-S3.5	ORIG	3.0E+03	=	03/25/09 14:00	3.0	3.5	Υ	Sediment Sample	Laboratory
IR21CB4SD0101	IR21CB4SD0101-SD6	ORIG	2.0E+03	=	05/01/09 09:00	6.0	6.5	Y	Sediment Sample	Laboratory
IR21MH2SD0101	IR21MH2SD0101-S4	ORIG	7.5E+02	=	03/25/09 13:50	3.0	3.5	Υ	Sediment Sample	Laboratory
olatile Organic Compounds					•					
Analyte 1,1,1,2-TETRACHLOROETHANE	CAS Number 630-20-6			_						
IR19D1M13SD0101 I,1,1-TRICHLOROETHANE	IR19D1M13SD0101-S7 71-55-6	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101 I,1,2,2-TETRACHLOROETHANE	IR19D1M13SD0101-S7 79-34-5	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101 I.1,2-TRICHLOROETHANE	IR19D1M13SD0101-S7 79-00-5	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101 ,1,2-TRICHLOROTRIFLUOROETHANE	IR19D1M13SD0101-S7 76-13-1	ORIG	2.2E-03	V	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101	IR19D1M13SD0101-S7	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Υ	Sediment Sample	Laboratory
TE:						^a FLAG	S			
Rinsate samples collected from neares	t catch basin or manhole.	-				= J U UJ	Detected Result Estimated Dete Nondetect Result Estimated Nonder	cted Result ult		•

2009 Analytical Results for Sediment, Concrete Chip and/or Rinsate Water Samples collected from the Storm Sewer System near IR19, IR21/Buildings 386/388/390 Area, PCB Site Building 678 AL#04 and PCB Site Building 830 UL#01

Site Summary Report for the Storm Sewer System near IR19, IR21/Buildings 386/388/390 Area, PCB Site Building 678 AL#04 and PCB Site Building 830 UL#01 in Investigation Area C2, Lennar Mare Island, Vallejo, California

Location of Sample	Sample Identifier	QA/QC Type	Value mg/kg	Flag ^a	Date and Time of Sample	Beginning	Depths Ending bgs)	Removed?	Type of Sample	Source of Measurement
Volatile Organic Compounds					-		,		٠,	
Analyte 1,1-DICHLOROETHANE	CAS Number 75-34-3					7				
IR19D1M13SD0101 1,1-DICHLOROETHENE	IR19D1M13SD0101-S7 75-35-4	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Υ	Sediment Sample	Laboratory
IR19D1M13SD0101 1,2,3-TRICHLOROPROPANE	IR19D1M13SD0101-S7 96-18-4	ORIG	2.2E-03	Ú	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101 1,2,4-TRICHLOROBENZENE	IR19D1M13SD0101-S7 120-82-1	ORIG	2.2E-03	υ	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101 1,2,4-TRIMETHYLBENZENE	IR19D1M13SD0101-S7 95-63-6	ORIG	2.2E-03	. U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101 1,2-DIBROMO-3-CHLOROPROPANE	IR19D1M13SD0101-S7 96-12-8	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101 1,2-DICHLOROBENZENE	IR19D1M13SD0101-S7 95-50-1	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101 1,2-DICHLOROETHANE	IR19D1M13SD0101-S7 107-06-2	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Υ .	Sediment Sample	Laboratory
• IR19D1M13SD0101 1,2-DICHLOROPROPANE	IR19D1M13SD0101-S7 78-87-5	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101 1,3,5-TRIMETHYLBENZENE	IR19D1M13SD0101-S7 108-67-8	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Υ -	Sediment Sample	Laboratory
IR19D1M13SD0101 1,3-DICHLOROBENZENE	IR19D1M13SD0101-S7 541-73-1	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	. Y	Sediment Sample	Laboratory
IR19D1M13SD0101	IR19D1M13SD0101-S7	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Υ	Sediment Sample	Laboratory
NOTE:				•		a FLAGS	3			
					`	= J	Detected Resu Estimated Dete			

\\gaia\datavalidation\dv\DataRequests\LMI_DataRequests.mdb (Report - 776)

Rinsate samples collected from nearest catch basin or manhole.

WB SO Detail Report, Generated 06/25/2010 1609, Page 4 of 10

Nondetect Result

Estimated Nondetect Result

2009 Analytical Results for Sediment, Concrete Chip and/or Rinsate Water Samples collected from the Storm Sewer System near IR19, IR21/Buildings 386/388/390 Area, PCB Site Building 678 AL#04 and PCB Site Building 830 UL#01

Site Summary Report for the Storm Sewer System near IR19, IR21/Buildings 386/388/390 Area, PCB Site Building 678 AL#04 and PCB Site Building 830 UL#01 in Investigation Area C2, Lennar Mare Island, Vallejo, California

CAS Number 106-46-7 IR19D1M13SD0101-S7 78-93-3	ORIG			· ·					
106-46-7 IR19D1M13SD0101-S7 78-93-3	ORIG			: '	_				
78-93-3	ORIG		•		•				
ID40D414420D0404.07		2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101-S7 95-49-8	ORIG	4.5E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101-S7 108-10-1	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101-S7 67-64-1	7 ORIG 4		U.	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101-S7 71-43-2	ORIG	1.1E-02	U ·	03/10/09 11:00	7.0	7.5	. Y	Sediment Sample	Laboratory
IR19D1M13SD0101-S7 108-86-1	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101-S7 75-27-4	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101-S7 75-25-2	ORIG	2.2E-03	U	03/10/09 11:00	. 7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101-S7 74-83-9	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101-S7 75-15-0	ORIG	2,2E-03	U	03/10/09 11:00	7.0	7.5	Υ	Sediment Sample	Laboratory
IR19D1M13SD0101-S7	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
					a FLAG = J U	Detected Resul Estimated Dete	cted Result		
	95-49-8 IR19D1M13SD0101-S7 108-10-1 IR19D1M13SD0101-S7 67-64-1 IR19D1M13SD0101-S7 71-43-2 IR19D1M13SD0101-S7 108-86-1 IR19D1M13SD0101-S7 75-27-4 IR19D1M13SD0101-S7 75-25-2 IR19D1M13SD0101-S7 77-483-9 IR19D1M13SD0101-S7 775-15-0	95-49-8 IR19D1M13SD0101-S7 ORIG 108-10-1 IR19D1M13SD0101-S7 ORIG 67-64-1 IR19D1M13SD0101-S7 ORIG 71-43-2 IR19D1M13SD0101-S7 ORIG 108-86-1 IR19D1M13SD0101-S7 ORIG 75-27-4 IR19D1M13SD0101-S7 ORIG 75-25-2 IR19D1M13SD0101-S7 ORIG 75-483-9 IR19D1M13SD0101-S7 ORIG 75-15-0 IR19D1M13SD0101-S7 ORIG	95-49-8 IR19D1M13SD0101-S7 ORIG 2.2E-03 108-10-1 IR19D1M13SD0101-S7 ORIG 4.5E-03 67-64-1 IR19D1M13SD0101-S7 ORIG 1.1E-02 71-43-2 IR19D1M13SD0101-S7 ORIG 2.2E-03 108-86-1 IR19D1M13SD0101-S7 ORIG 2.2E-03 75-27-4 IR19D1M13SD0101-S7 ORIG 2.2E-03 75-25-2 IR19D1M13SD0101-S7 ORIG 2.2E-03 75-483-9 IR19D1M13SD0101-S7 ORIG 2.2E-03 75-15-0 IR19D1M13SD0101-S7 ORIG 2.2E-03	IR19D1M13SD0101-S7	IR19D1M13SD0101-S7 ORIG 2.2E-03 U 03/10/09 11:00 IR19D1M13SD0101-S7 ORIG 4.5E-03 U 03/10/09 11:00 IR19D1M13SD0101-S7 ORIG 1.1E-02 U 03/10/09 11:00 IR19D1M13SD0101-S7 ORIG 2.2E-03 U 03/10/09 11:00	R19D1M13SD0101-S7 ORIG 2.2E-03 U 03/10/09 11:00 7.0 R19D1M13SD0101-S7 ORIG 4.5E-03 U 03/10/09 11:00 7.0 R19D1M13SD0101-S7 ORIG 1.1E-02 U 03/10/09 11:00 7.0 R19D1M13SD0101-S7 ORIG 2.2E-03 U 03/10/09 11:00 7.0	R19D1M13SD0101-S7 ORIG 2.2E-03 U 03/10/09 11:00 7.0 7.5 R19D1M13SD0101-S7 ORIG 4.5E-03 U 03/10/09 11:00 7.0 7.5 R19D1M13SD0101-S7 ORIG 1.1E-02 U 03/10/09 11:00 7.0 7.5 R19D1M13SD0101-S7 ORIG 2.2E-03 U 03/10/09 11:00 7.0 7.5	R19D1M13SD0101-S7 ORIG 2.2E-03 U 03/10/09 11:00 7.0 7.5 Y 108-10-1 R19D1M13SD0101-S7 ORIG 4.5E-03 U 03/10/09 11:00 7.0 7.5 Y 7.5	R19D1M13SD0101-S7 ORIG 2.2E-03 U 03/10/09 11:00 7.0 7.5 Y Sediment Sample

2009 Analytical Results for Sediment, Concrete Chip and/or Rinsate Water Samples collected from the Storm Sewer System near IR19, IR21/Buildings 386/388/390 Area, PCB Site Building 678 AL#04 and PCB Site Building 830 UL#01

Site Summary Report for the Storm Sewer System near IR19, IR21/Buildings 386/388/390 Area, PCB Site Building 678 AL#04 and PCB Site Building 830 UL#01 in Investigation Area C2, Lennar Mare Island, Vallejo, California

-				а	Date and	Sample [
Location of Sample	Sample Identifier	QA/QC Type	Value mg/kg	Flag	Time of Sample	Beginning (feet b		Removed?	Type of Sample	Source of Measuremen
/olatile Organic Compounds				<u> </u>						
Analyte CARBON TETRACHLORIDE	CAS Number 56-23-5						_			
IR19D1M13SD0101 CHLOROBENZENE	IR19D1M13SD0101-S7 108-90-7	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101 CHLOROETHANE	IR19D1M13SD0101-S7 75-00-3	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Υ	Sediment Sample	Laboratory
IR19D1M13SD0101 CHLOROFORM	IR19D1M13SD0101-S7 67-66-3	ORIG	2.2E-03	U	03/10/09 11:00	7.0 ′	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101 CHLOROMETHANE	IR19D1M13SD0101-S7 74-87-3	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101 CIS-1,2-DICHLOROETHENE	IR19D1M13SD0101-S7 156-59-2	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101 DIBROMOCHLOROMETHANE	IR19D1M13SD0101-S7 124-48-1	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101 DICHLORODIFLUOROMETHANE	IR19D1M13SD0101-S7 75-71-8	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101 ETHYLBENZENE	IR19D1M13SD0101-S7 100-41-4	ORIG	3.3E-03	UJ	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101 ETHYLENE DIBROMIDE	IR19D1M13SD0101-S7	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	. Y	Sediment Sample	Laboratory
IR19D1M13SD0101 . ISOPROPYLBENZENE	IR19D1M13SD0101-S7 98-82-8	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101	IR19D1M13SD0101-S7	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
OTE:			·			^a FLAGS				
							Detected Resu	I +		

Rinsate samples collected from nearest catch basin or manhole.

Detected Result

Estimated Detected Result

U Nondetect-Result

J Estimated Nondetect Result

2009 Analytical Results for Sediment, Concrete Chip and/or Rinsate Water Samples collected from the Storm Sewer System near IR19, IR21/Buildings 386/388/390 Area, PCB Site Building 678 AL#04 and PCB Site Building 830 UL#01

Site Summary Report for the Storm Sewer System near IR19, IR21/Buildings 386/388/390 Area, PCB Site Building 678 AL#04 and PCB Site Building 830 UL#01 in Investigation Area C2, Lennar Mare Island, Vallejo, California

Location of Sample Volatile Organic Compounds	Sample Identifier	QA/QC Type	Value mg/kg	Flag	Date and Time of Sample	Beginning	e Depths g Ending t bgs)	Removed?	Type of Sample	Source of Measurement
/olatile Organic Compounds										
Analyte M,P-XYLENE	CAS Number 108-38-3/1									
IR19D1M13SD0101 METHYL TERTIARY BUTYLETHER	IR19D1M13SD0101-S7 1634-04-4	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101 METHYLENE CHLORIDE	IR19D1M13SD0101-S7 75-09-2	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101 N-BUTYLBENZENE	IR19D1M13SD0101-S7 104-51-8	ORIG	9.0E-03	U	03/10/09 11:00	7.0	7.5	. У	Sediment Sample	Laboratory
IR19D1M13SD0101 N-PROPYLBENZENE	IR19D1M13SD0101-S7 103-65-1	ORIG	2.3E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101 D-XYLENE	IR19D1M13SD0101-S7 95-47-6	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101 SEC-BUTYLBENZENE	IR19D1M13SD0101-S7 135-98-8	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101 STYRENE	IR19D1M13SD0101-S7 100-42-5	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101 ERT-BUTYLBENZENE	IR19D1M13SD0101-S7 98-06-6	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101 ETRACHLOROETHENE	IR19D1M13SD0101-S7 127-18-4	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101 OLUENE	IR19D1M13SD0101-S7 108-88-3	ORIG	2.6E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101	IR19D1M13SD0101-S7	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
DTE:	······································					^a FLAG				
Rinsate samples collected from neares	t catch basin or manhole.					= J U UJ	Detected Resu Estimated Dete Nondetect Res Estimated Non-	ected Result		

\\gaia\datavalidation\dv\DataRequests\LMI_DataRequests.mdb (Report - 776)

2009 Analytical Results for Sediment, Concrete Chip and/or Rinsate Water Samples collected from the Storm Sewer System near IR19, IR21/Buildings 386/388/390 Area, PCB Site Building 678 AL#04 and PCB Site Building 830 UL#01

Site Summary Report for the Storm Sewer System near IR19, IR21/Buildings 386/388/390 Area, PCB Site Building 678 AL#04 and PCB Site Building 830 UL#01 in Investigation Area C2, Lennar Mare Island, Vallejo, California

Location of Sample	Sample Identifier	QA/QC Type	Value mg/kg	Flag ^a	Date and Time of Sample	Beginnin	e Depths g Ending et bgs)	Removed?	Type of Sample	Source of Measurement
Volatile Organic Compounds										•
Analyte TRANS-1,2-DICHLOROETHENE	CAS Number 156-60-5									
IR19D1M13SD0101 TRICHLOROETHENE	IR19D1M13SD0101-S7 79-01-6	ORIG	2.2E-03	U	03/10/09 11:00	7.0	7.5	Υ	Sediment Sample	Laboratory
IR19D1M13SD0101 VINYL CHLORIDE	IR19D1M13SD0101-S7 75-01-4	ORIG	. 2.2E-03	U	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
IR19D1M13SD0101	IR19D1M13SD0101-S7	ORIG	2.2E-03	Ų	03/10/09 11:00	7.0	7.5	Y	Sediment Sample	Laboratory
PCB Compounds										
Analyte AROCLOR-1016	CAS Number 12674-11-2			·						
IR21CB1SD0101 AROCLOR-1221	IR21CB1SD0101-S6 11104-28-2	ORIG	3.0E-03	U	03/10/09 10:30	6.0	6.5	Y	Sediment Sample	Laboratory
IR21CB1SD0101 AROCLOR-1232	IR21CB1SD0101-S6 11141-16-5	ORIG	5.9E-03	U	03/10/09 10:30	6.0	6.5	Y	Sediment Sample	Laboratory
IR21CB1SD0101 AROCLOR-1242	IR21CB1SD0101-S6 53469-21-9	ORIG	3.9E-03	U.	03/10/09 10:30	6.0	6.5	Y	Sediment Sample	Laboratory
IR21CB1SD0101 AROCLOR-1248	IR21CB1SD0101-S6 12672-29-6	ORIG	2.8E-03	U	03/10/09 10:30	6.0	6.5	Y	Sediment Sample	Laboratory
IR21CB1SD0101 AROCLOR-1254	IR21CB1SD0101-S6 11097-69-1	ORIG	1.2E-03	U	03/10/09 10:30	6.0	6.5	Y	Sediment Sample	Laboratory
IR21CB1SD0101 AROCLOR-1260	IR21CB1SD0101-S6 11096-82-5	` ORIG	1.2E-01	=	03/10/09 10:30	6.0	. 6.5	Υ _{`2}	Sediment Sample	Laboratory
IR21CB1SD0101	IR21CB1SD0101-S6	ORIG	8.1E-02	=	03/10/09 10:30	6.0	6.5	Υ	Sediment Sample	Laboratory
NOTE: Rinsate samples collected from neares	t catch basin or manhole.					^a FLAG = J U UJ	Detected Resul Estimated Dete Nondetect Resul Estimated Nonde	cted Result ult		

WB SO Detail Report, Generated 06/25/2010 1609, Page 8 of 10

2009 Analytical Results for Sediment, Concrete Chip and/or Rinsate Water Samples collected from the Storm Sewer System near IR19, IR21/Buildings 386/388/390 Area, PCB Site Building 678 AL#04 and PCB Site Building 830 UL#01

Site Summary Report for the Storm Sewer System near IR19, IR21/Buildings 386/388/390 Area, PCB Site Building 678 AL#04 and PCB Site Building 830 UL#01 in Investigation Area C2, Lennar Mare Island, Vallejo, California

Location of Sample	Sample Identifier	QA/QC	Value	Flag ^a	Date and Time	Sample Beginning	Ending	Removed?	Type of	Source of
PCB Compounds		Туре	mg/kg		of Sample	(feet I	ogs)		Sample	Measurement
Analyte AROCLOR-1262	CAS Number 37324-23-5									
IR21CB1SD0101 AROCLOR-1268	IR21CB1SD0101-S6 11100-14-4	ORIG	1.5E-02	U	03/10/09 10:30	6.0	6.5	. Y	Sediment Sample	Laboratory
IR21CB1SD0101	IR21CB1SD0101-S6	ORIG	1.5E-02	U	03/10/09 10:30	6.0	6.5	Υ	Sediment Sample	Laboratory
Metals										
Analyte LEAD	CAS Number 7439-92-1									
IR21CB1SD0101	IR21CB1SD0101-S6	ORIG	8.4E+03	=	03/10/09 10:30	6.0	6.5	Υ	Sediment Sample	Laboratory
IR21CB2SD0101	IR21CB2SD0101-S3	ORIG	1.4E+02	=	03/25/09 15:40	3.0	3.5	Υ	Sediment Sample	Laboratory
IR21CB3SD0101	IR21CB3SD0101-S3.5	ORIG	2.4E+02	=	03/25/09 14:00	3.0	3.5	Υ	Sediment Sample	Laboratory
IR21CB4SD0101	IR21CB4SD0101-SD6	. ORIG	2.5E+02	=	05/01/09 09:00	6.0	6.5	Y	Sediment Sample	Laboratory
IR21MH2SD0101	IR21MH2SD0101-S4	. ORIG	2.1E+02	=	03/25/09 13:50	3.0	3.5	Υ	Sediment Sample	Laboratory



2009 Analytical Results for Sediment, Concrete Chip and/or Rinsate Water Samples collected from the Storm Sewer System near IR19, IR21/Buildings 386/388/390 Area, PCB Site Building 678 AL#04 and PCB Site Building 830 UL#01

Site Summary Report for the Storm Sewer System near IR19, IR21/Buildings 386/388/390 Area, PCB Site Building 678 AL#04 and PCB Site Building 830 UL#01 in Investigation Area C2, Lennar Mare Island, Vallejo, California

	Location of Sample	Sample Identifier	QA/QC Type	Value (µg/L)	Flag	Date and Time of Sample	Sample Beginning (feet	Ending	Removed?	Type of Sample	Source of Measurement
Petroleun	n Hydrocarbon Compo	ounds									
Analyte DIESEL		CAS Number DRO		_		4444				•	
	IR21SSCB1CB2	IR21SSCB1CB2-W	ORIG	1.5E+02	J	03/24/10 15:00	3.0	3.5	Y	Rinsate	Laboratory
	IR21SSCB1MH5	IR21SSCB1MH5-W	ORIG	5.9E+02	J	03/25/10 10:30	3.0	3.5	Y	Rinsate	Laboratory
	IR21SSMH4MH2	IR21SSMH4MH2-W	ORIG	3.6E+02	J	03/26/10 14:15	3.0	3.5	Υ	Rinsate	Laboratory
MOTOR OIL	<u></u>	MRO									
	IR21SSCB1CB2	IR21SSCB1CB2-W	ORIG	2.4E+02	J	03/24/10 15:00	3.0	3.5	Y	Rinsate	Laboratory
	IR21SSCB1MH5	IR21SSCB1MH5-W	ORIG	5.4E+02	=	03/25/10 10:30	3.0	3.5	Y	Rinsate	Laboratory
	IR21SSMH4MH2	IR21SSMH4MH2-W	ORIG	8.6E+02	=	03/26/10 14:15	3.0	3.5	Y	Rinsate	Laboratory
/letals											
Analyte LEAD		CAS Númber 7439-92-1		,							
	IR21SSCB1CB2	IR21SSCB1CB2-W	ORIG	3.7E+00	=	03/24/10 15:00	3.0	3.5	Y	Rinsate	Laboratory
	IR21SSCB1MH5	IR21SSCB1MH5-W	ORIG	4.5E+02	=	03/25/10 10:30	3.0	3.5	Y	Rinsate	Laboratory
	IR21SSMH4MH2	IR21SSMH4MH2-W	ORIG	1.0E+03	=	03/26/10 14:15	3.0	3.5	Y	Rinsate	Laboratory

NOTE: a FLAGS

Rinsate samples collected from nearest catch basin or manhole.

= Detected Result

J Estimated Detected Result

J Nondetect Result

J Estimated Nondetect Result

Appendix B Unvalidated Laboratory Analytical Reports

Appendix C Rinsate Wastewater Analytical Results and Permit to Discharge to Sanitary Sewer System

Zigizz

Chain of Custody Record COC Number: CTL-IDN	W-193		C	:H:	2 IV	۱H	ILL	3	30/2	2010	10:4	15:47	АМ	P	age	1 of	1					
Project Name Mare Island Location Mare Island Task Order Project: IDW IR21SS Flushing Project Number 264204.16.A4.04 Project Manager Paula Bolio Sample Manager Roger Lucich (925) 250-4441																						
Turnaround Time 2 Days PO Number 264204.16.A4.04 Sample ID Sample Date/Time Type Matri	ix #Conti	ainers	Preserv	EPA150.1	EPA1664	EPA200/245	EPA335.2	EPA420.1	EPA608													
IDWIR21SSCOV001-W 30-Mar-10 10:15 N Wate)r			1									1				T	:	1			į
Field Filter	red:1	1	4'C	V	1.7								_ [3;-				-1			ĬΕ	
Field Filter	red:1	l N	IaOH, 4°C	1			•	Ī,			_][
Field Filter	red: 1	H	NO3, 4'C	ΙŪ		¥				U;			110					310	210	1	ΉĽ	
Field Filter	red:	2	4'C	10		\Box	<u></u>		✓			Ξ.	Į.		7)[!		3/1				3 0	1
Field Filter	red:4	4	4'C	ΠÔ	¥			✓			3			-11					<u> </u>		- 1 -	
Tot	al Contai	ners:	- 18	<u> </u>						1-	- +		i	!	-1-	!	1	7			T	1
THE PART AND PORT AND COMMUNICATION OF A COMMUNICATION OF THE PART AND A COMMUNICATION OF THE			(1)) h	<u></u>						er serie					8 9 7. <u></u>	- m - im				- Angelo	

0.0

MS = Matrix Spike	SD = Matrix Spike Duplic	ate			
	Signatures	Date/Time	Shipping Details	;	Special Instructions:
Approved by			Method of Shipment:	ATTN:	:
Sampled by	7 1/1	/			
Relinquished by	ogent by	3-30-100 1100	On Ice: yes / no	Sample Custody	
Received by		3/30/10	Airbill No:	and	December
Relinquished by	7 any	1445	Lab Name: Curtis & Tompkins, Ltd.	Lisa Brooker	: Report Copy to Mark Cichy
Received by			Lab Phone: (510) 486-0925	Lisa Diookei	(520) 229-3274

COOLER RECEIPT CHECKLIST



Login # 719122 Date Received 3-30-10 Number of coolers /	
Client CI Project MAN ISWAN.	
Date Opened 3-70-10 By (print) S EVAS (sign) Date Logged in By (print) (sign)	_
1. Did cooler come with a shipping slip (airbill, etc) YES (NO Shipping info	
2A. Were custody seals present? Notes (circle) on cooler on samples No How many Name Name Date The No Notes No No Notes No Notes No No Notes No No Notes No No No	//A.
Bubble Wrap	
Type of ice used: Wet Blue/Gel None Temp(°C)	•
Samples Received on ice & cold without a temperature blank	
- •	
El Sampler received on ice directly from the field. Cooling process had begun	
Samples received on ice directly from the field. Cooling process had begun 8. Were Method 5035 sampling containers present? YES NO If YES, what time were they transferred to freezer?	D
8. Were Method 5035 sampling containers present? YES NO If YES, what time were they transferred to freezer? 9. Did all bottles arrive unbroken/unopened? NO	<u> </u>
8. Were Method 5035 sampling containers present? If YES, what time were they transferred to freezer? 9. Did all bottles arrive unbroken/unopened? 10. Are samples in the appropriate containers for indicated tests? NO))
8. Were Method 5035 sampling containers present? If YES, what time were they transferred to freezer? 9. Did all bottles arrive unbroken/unopened? 10. Are samples in the appropriate containers for indicated tests? NO 11. Are sample labels present, in good condition and complete?)))
8. Were Method 5035 sampling containers present? If YES, what time were they transferred to freezer? 9. Did all bottles arrive unbroken/unopened? 10. Are samples in the appropriate containers for indicated tests? 11. Are sample labels present, in good condition and complete? 12. Do the sample labels agree with custody papers? NO)
8. Were Method 5035 sampling containers present? If YES, what time were they transferred to freezer? 9. Did all bottles arrive unbroken/unopened? 10. Are samples in the appropriate containers for indicated tests? 11. Are sample labels present, in good condition and complete? 12. Do the sample labels agree with custody papers? 13. Was sufficient amount of sample sent for tests requested? 15. NO)
8. Were Method 5035 sampling containers present? If YES, what time were they transferred to freezer? 9. Did all bottles arrive unbroken/unopened? 10. Are samples in the appropriate containers for indicated tests? 11. Are sample labels present, in good condition and complete? 12. Do the sample labels agree with custody papers? 13. Was sufficient amount of sample sent for tests requested? 14. Are the samples appropriately preserved?)
If YES, what time were they transferred to freezer? 9. Did all bottles arrive unbroken/unopened? 10. Are samples in the appropriate containers for indicated tests? 11. Are sample labels present, in good condition and complete? 12. Do the sample labels agree with custody papers? 13. Was sufficient amount of sample sent for tests requested? 14. Are the samples appropriately preserved? 15. Are bubbles > 6mm absent in VOA samples? 16. Wes Method 5035 sampling containers present? 17. NO 18. NO 19. N)))))
8. Were Method 5035 sampling containers present? If YES, what time were they transferred to freezer? 9. Did all bottles arrive unbroken/unopened? 10. Are samples in the appropriate containers for indicated tests? 11. Are sample labels present, in good condition and complete? 12. Do the sample labels agree with custody papers? 13. Was sufficient amount of sample sent for tests requested? 14. Are the samples appropriately preserved?)))))
If YES, what time were they transferred to freezer? 2. Did all bottles arrive unbroken/unopened? 3. One samples in the appropriate containers for indicated tests? 4. Are sample labels present, in good condition and complete? 4. Are the samples appropriately preserved? 4. Are the samples appropriately preserved? 4. Are bubbles > 6mm absent in VOA samples? 4. Was the client contacted concerning this sample delivery? 4. Was the client contacted concerning this sample delivery? 4. One was called? 5. One was called? 6. Was the client contacted concerning this sample delivery? 6. Was the Client Contacted Concerning this sample delivery? 6. Was the Client Contacted Concerning this sample delivery? 6. One was called? 6. Date: 6. Comments)))))
If YES, what time were they transferred to freezer? Do Did all bottles arrive unbroken/unopened? O Did all bettles arrive unbroken/unopened? O Did all be)))))
If YES, what time were they transferred to freezer? 2. Did all bottles arrive unbroken/unopened? 3. One samples in the appropriate containers for indicated tests? 4. Are sample labels present, in good condition and complete? 4. Are the samples appropriately preserved? 4. Are the samples appropriately preserved? 4. Are bubbles > 6mm absent in VOA samples? 4. Was the client contacted concerning this sample delivery? 4. Was the client contacted concerning this sample delivery? 4. One was called? 5. One was called? 6. Was the client contacted concerning this sample delivery? 6. Was the Client Contacted Concerning this sample delivery? 6. Was the Client Contacted Concerning this sample delivery? 6. One was called? 6. Date: 6. Comments)))))
If YES, what time were they transferred to freezer? 9. Did all bottles arrive umbroken/unopened? 10. Are samples in the appropriate containers for indicated tests? 11. Are sample labels present, in good condition and complete? 12. Do the sample labels agree with custody papers? 13. Was sufficient amount of sample sent for tests requested? 14. Are the samples appropriately preserved? 15. Are bubbles > 6mm absent in VOA samples? 16. Was the client contacted concerning this sample delivery? 17. If YES, Who was called? 18. NO 19.)))))
If YES, what time were they transferred to freezer? Did all bottles arrive unbroken/unopened? On Are samples in the appropriate containers for indicated tests? In Are sample labels present, in good condition and complete? Do the sample labels agree with custody papers? In Are the samples appropriately preserved? In Are the sample abelians appropriately preserved? In Are the sample labels agree with custody papers? In Are samples in the appropriate containers for indicated tests? NO N/A In Are sample labels present, in good condition and complete? In Are samples in the appropriate containers for indicated tests? NO N/A In Are sample labels present, in good condition and complete? In Are samples in the appropriate containers for indicated tests? NO N/A In Are sample labels present, in good condition and complete? In NO In Are sample labels present, in good condition and complete? In NO In Are sample labels present, in good condition and complete? In NO In Are sample labels present, in good condition and complete? In NO In Are sample labels present, in good condition and complete? In NO In Are sample labels present, in good condition and complete? In NO In Are sample labels present, in good condition and complete? In NO In Are sample labels present, in good condition and complete? In NO In Are sample labels present, in g)))))

SOP Volume:

Client Services

Section:

1.1.2

Page:

1 of 1

Rev. 6 Number 1 of 3

Effective: 23 July 2008 Z:\qc\forms\checklists\Cooler Receipt Checklist_rv6.doc

Curtis & Tompkins Sample Preservation for 219122

<u>Sample</u>	pH:	<2 :	>12	Other
-001a		H	[]	·
b.			[]	: -
С		-	į	:
đ		1	[]	:
е		1	į	:
f			[]	
g		1	Ĺ	:
$reve{ ilde{h}}$, ī	įį	
· i		[]:	[]	
i		î î	î î	,
k		įί	Ϊí	

rate: 3/2/10



	Pest	icides	
Lab #:	219122	Location:	IR21 Storm Sewer Flushing
Client:	CH2M Hill Constructors Inc.	Prep:	EPA 608
Project#:	264204.16.A4.04	Analysis:	EPA 608
Field ID:	IDWIR21SSCOV001-W	Batch#:	161476
Lab ID:	219122-001	Sampled:	03/30/10
Matrix:	Water	Received:	03/30/10
Units:	ug/L	Prepared:	03/30/10
Diln Fac:	1.000	Analyzed:	04/02/10

Analyte	Result	RL	MDL
alpha-BHC	ND	0.05	0.007
beta-BHC	ND	0.05	0.007
gamma-BHC	ND	0.05	0.007
delta-BHC	ND	0.05	0.008
Heptachlor	ND .	0.05	0.009
Aldrin	ND	0.05	0.006
Heptachlor epoxide	ND	0.1	0.006
Endosulfan I	ND	0.05	0.006
Dieldrin	ND	0.1	0.01
4,4'-DDE	ND	0.1	0.02
Endrin	ND	0.1	0.02
Endosulfan II	ND ·	0.1	0.01
Endosulfan sulfate	ND	0.1	0.02
4,4'-DDD	ND	0.1	0.02
Endrin aldehyde	ND	0.1	0.02
4,4'-DDT	ND	0.1	0.02
alpha-Chlordane	ND	0.05	0.007
gamma-Chlordane	0.008 C J	0.05	0.007
Methoxychlor	ND	0.5	0.1
Endrin ketone	ND	0.1	0.02
Toxaphene	ND	1.0	0.3

	%REC	Limits	2.30	t Marien	A CONTRACT TO THE PARTY OF THE
TCMX	65	45-125			
Decachlorobiphenyl	67_	34-133			

C= Presence confirmed, but RPD between columns exceeds 40%

J= Estimated value

ND= Not Detected at or above MDL

RL= Reporting Limit

MDL= Method Detection Limit



	Pesi	cicides 📡 🕆	
Lab #:	219122	Location:	IR21 Storm Sewer Flushing
Client:	CH2M Hill Constructors Inc.	Prep:	EPA 608
Project#:	264204.16.A4.04	Analysis:	EPA 608
Type:	BLANK	Diln Fac:	1.000
Lab ID:	QC538320	Batch#:	161476
Matrix:	Water	Prepared:	03/30/10
Units:	ug/L	Analyzed:	04/02/10

Analyte 🥢	Result	RL RL	MOL NEW YEAR
alpha-BHC	ND .	0.05	0.007
beta-BHC	ND	0.05	0.007
gamma-BHC	ND	0.05	0.007
delta-BHC	ND	0.05	0.008
Heptachlor	ND	. 0.05	0.009
Aldrin	ND	0.05	0.006
Heptachlor epoxide	ND	0.1	0.006
Endosulfan I	ND	0.05	0.006
Dieldrin `	ND	0.1	0.01
4,4'-DDE	ND	0.1	0.02
Endrin	ND	0.1	0.02
Endosulfan II	ND	0.1	0.01
Endosulfan sulfate	ND	0.1	0.02
4,4'-DDD	ND	0.1	0.02
Endrin aldehyde	ND	0.1	. 0.02
4,4'-DDT	ND	0.1	0.02
alpha-Chlordane	ND	0.05	0.007
gamma-Chlordane	, ND	0.05	0.007
Methoxychlor	N -D	0.5	0.1
Endrin ketone	ND	0.1	0.02
Toxaphene	ND	1.0	0.3

Surrogate	%REC	Limits			 4.
TCMX	86	45-125		 	\neg
Decachlorobiphenyl	95	34-133			

RL= Reporting Limit

MDL= Method Detection Limit



	Pest	icides	
Lab #:	219122	Location:	IR21 Storm Sewer Flushing
Client:	CH2M Hill Constructors Inc.	Prep:	EPA 608
Project#:	26 <u>4204.16.</u> A4.04	_Analysis:	EPA 608
Matrix:	Water	Batch#:	161476
Units:	ug/L	Prepared:	03/30/10
Diln Fac:	1.000	Analyzed:	04/02/10

Type:

BS

Lab ID:

QC538321

Analyte	Spiked	Result	%REC	Limits
alpha-BHC	0.2000	0.1830	91	75-125
beta-BHC	0.2000	0.1859	93	51-125
gamma-BHC	0.2000	0.1873	94	73-125
Heptachlor	0.2000	0.1781	89	45-128
Aldrin	0.2000	0.1730	87	47-125
Heptachlor epoxide	0.2000	0.1881	94	53-134
Dieldrin	0.4000	0.3514	88	42-132
4,4'-DDE	0.4000	0.3899	97	45-139
Endrin	0.4000	0.3527	88	43-134
Endosulfan sulfate	0.4000	0.3646	91	46-141
4,4'-DDD	0.4000	0.3737 b	93	48-136
4,4'-DDT	0.4000	0.4190	105	34-143
Methoxychlor	2.000	1.828	91	73-142

Surrogate	%REC	Limits	the state of the s
TCMX	82	45-125	
Decachlorobiphenyl	90	34-133	

Type:

BSD

Lab ID:

QC538322

Analyte	Spiked	Result %	REC Limits	RPD	Lim
alpha-BHC	0.2000	0.1738 87	75-125	5	30
beta-BHC	0.2000	0.1695 85	51-125	9	30
gamma-BHC -	0.2000	0.1741 87	73-125	7	30
Heptachlor	0.2000	0.1625 81	45-128	9	30
Aldrin	0.2000	0.1614 81	47-125	7	30
Heptachlor epoxide	0.2000	0.1756 88	53-134	7	30
Dieldrin	0.4000	0.3306 83	42-132	6	30
4,4'-DDE	0.4000	0.3565 89	45-139	9	30
Endrin	0.4000	0.3247 81	43-134	8	30
Endosulfan sulfate	0.4000	0.3382 85	46-141	8	30
4,4'-DDD	0.4000	0.3390 b 85	48-136	10	30
4,4'-DDT	0.4000	0.3701 93	34-143	12	30
<u>Methoxychlor</u>	2.000	1.636 82	73-142	11	30

Surrogate	%REC	Limits	35 a	1.757 1.54 1.5	. 4	
TCMX	78	45-125				
Decachlorobiphenyl	84	34-133				



	P	CB	
Lab #:	219122	Location:	IR21 Storm Sewer Flushing
Client:	CH2M Hill Constructors Inc.	Prep:	EPA 608
Project#:	264204.16.A4.04	Analysis:	EPA 608
Field ID:	IDWIR21SSCOV001-W	Sampled:	03/30/10
Matrix:	Water	Received:	03/30/10
Units:	ug/L	Prepared:	03/30/10
Diln Fac:	1.000	Analyzed:	04/01/10
Batch#:	161477		

Type:

SAMPLE

Lab ID: 219122-001

Analyte	Result	RL .	MDI
Aroclor-1016	ND	0.50	0.12
Aroclor-1221	ND	1.0	0.32
Aroclor-1232	ND	0.50	0.12
Aroclor-1242	ND .	0.50	0.084
Aroclor-1248	ND	0.50	0.14
Aroclor-1254	ND	0.50	0.12
Aroclor-1260	1.3	0.50	0.062
Aroclor-1262	ND.	0.50	
Aroclor-1268	ND	0.50	

Surrogate	28 - 18 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	₹R	EC.Limits	F - KROZY s	1.48g		\$. 4980	Charles .
TCMX		86	34-133					
Decachlorobiphenyl		82	34-133					

Type:

BLANK

Lab ID:

QC538323

Analyte	Result	RL .	MOL
Aroclor-1016	ND	0.50	0.12
Aroclor-1221	ND	1.0	0.32
Aroclor-1232	ND	0.50	0.12
Aroclor-1242	ND	0.50	0.084
Aroclor-1248	ND	0.50	0.14
Aroclor-1254	ND	0.50	0.12
Aroclor-1260	ND	0.50	0.062
Aroclor-1262	· ND	0.50	
Aroclor-1268	ND	0.50	

Surrogate	%REC	Limits			
TCMX	81	34-133		•	
Decachlorobiphenyl	88	34-133			

ND= Not Detected

RL= Reporting Limit

MDL= Method Detection Limit

Page 1 of 1



	I	PCB	
Lab #:	219122	Location:	IR21 Storm Sewer Flushing
Client:	CH2M Hill Constructors Inc.	Prep:	EPA 608
Project#:	264204.16.A4.04	Analysis:	EPA 608
Matrix:	Water	Batch#:	161477
Units:	ug/L	Prepared:	03/30/10
Diln Fac:	1.000	Analyzed:	04/01/10

Type:

BS

Lab ID:

QC538324

Analyte	Spiked	Result	₹REC	Limits	KABU BALA
Aroclor-1016	5.000	4.659	93	54-125	·
Aroclor-1260	5.000	4.655	93	41-126	ı

Surrogate	%REC	Limits
TCMX	82	34-133
Decachlorobiphenyl	82	34-133

Type:

BSD

Lab ID:

QC538325

Analyte	Spiked	Result	%REC	: SLimits	RPD	Lim
Aroclor-1016	5.000	4.900	. 98	54-125	5	30
Aroclor-1260	5.000	5.110	. 102	41-126	9	30

	Surrogate 🧷 🚧	%REC	Limits	
I	TCMX	85	34-133	
1	Decachlorobiphenyl	 93	34-133	



	Metals Anal		
Lab #:	219122	Project#:	264204.16.A4.04
Client:	CH2M Hill Constructors Inc.	Location:	IR21 Storm Sewer Flushing
Field ID:	IDWIR21SSCOV001-W	Sampled:	03/30/10
Lab ID:	219122-001	Received:	03/30/10
Matrix:	Water	Prepared:	03/31/10
Units:	ug/L		

Analyte 🥍	R	∍sųlt	RL	MDL	Diln Fac	Batch#	Analyzed	Prep	Analysis
Arsenic		8.8	1.0	0.11	5.000	161529	04/01/10	EPA 200.8	EPA 200.8
Beryllium	ND		1.0	0.12	5.000	161529	04/01/10	EPA 200.8	EPA 200.8
Cadmium		0.31 J	1.0	0.083	5.000	161529	04/01/10	EPA 200.8	EPA 200.8
Chromium		3.2	1.0	0.15	5.000	161529	04/01/10	EPA 200.8	EPA 200.8
Copper		24	1.0	0.13	5.000	161529	04/01/10	EPA 200.8	EPA 200.8
Lead		34	1.0	0.15	5.000	161529	04/01/10	EPA 200.8	EPA 200.8
Mercury		2.3	0.20	0.015	1.000	161484	03/31/10	METHOD	EPA 245.1
Nickel	ť	11	1.0	0.11	5.000	161529	04/01/10	EPA 200.8	EPA 200.8
Selenium	(0.44 J	1.0	0.15	5.000	161529	04/01/10	EPA 200.8	EPA 200.8
Silver	ND .		1.0	0.068	5.000	161529	04/01/10	EPA 200.8	EPA 200.8
Zinc		85	5.0	1.1	5.000	161529	04/01/10	EPA 200.8	EPA 200.8

J= Estimated value

 $^{{\}tt ND=\ Not\ Detected\ at\ or\ above\ MDL}$

RL= Reporting Limit

MDL= Method Detection Limit



	Metals Anal	ytical Repo	ct
Lab #:	219122	Location:	IR21 Storm Sewer Flushing ,
Client:	CH2M Hill Constructors Inc.	Prep:	METHOD
Project#:	264204.16.A4.04	Analysis:	EPA 245.1
Analyte:	Mercury	Diln Fac:	1.000
Type:	BLANK	Batch#:	161484
Lab ID:	QC538362	Prepared:	03/31/10
Matrix:	Water	Analyzed:	03/31/10
Units:	ug/L		·

Result 🐘 🦠	RL .	MDL	MARTINE PARTY OF THE PROPERTY OF THE SECOND
ND ·	0.20	0.015	

ND= Not Detected at or above MDL

RL= Reporting Limit

MDL= Method Detection Limit

Page 1 of 1



	Metals, Anal	ytical Report	So I and parallely department of the Control of the
Lab #:	219122	Location:	IR21 Storm Sewer Flushing
Client:	.CH2M Hill Constructors Inc.	Prep:	METHOD
Project#:	264204.16.A4.04	Analysis:	EPA 245.1
Analyte: \	Mercury	Batch#:	161484
Matrix:	Water	Prepared:	03/31/10
Units:	ug/L	Analyzed:	03/31/10
Diln Fac:	1.000		

Туре	Lab ID	Spiked	Result	%REC	Limits	, RPD	Lim	Comment of the Commen
BS	QC538363	2.500	2.500	100	77-124			
BSD	QC538364	2.500	2.520	101	77-124	1	12	·



	Metals Anal	ytical Report	
Lab #:	219122	Location:	IR21 Storm Sewer Flushing
Client:	CH2M Hill Constructors Inc.	Prep:	METHOD
Project#:	264204.16.A4.04	Analysis:	EPA 245.1
Analyte:	Mercury	Batch#:	161484
Field ID:	IDWIR21SSCOV001-W	Sampled:	03/30/10
MSS Lab ID:	219122-001	Received:	03/30/10
Matrix:	Water	Prepared:	03/31/10
Units:	ug/L	Analyzed:	03/31/10
Diln Fac:	1.000		

Туре	Lab, ID 🦟	MSS Result	Spiked	Result	%REC	Limits	\mathtt{RPD}_{k} \mathtt{Lim}_{k}
MS	QC538365	2.330	2.500	4.800	99	53-149	
MSD .	QC538366		2.500	4.830	100	53-149	1 19



	Metals Anal	lytical Report	
Lab #:	219122	Location:	IR21 Storm Sewer Flushing
Client:	CH2M-Hill Constructors Inc.	Prep:	METHOD
Project#:	264204.16.A4.04	Analysis:	EPA 245.1
Analyte:	Mercury	Units:	ug/L
Field ID:	IDWIR21SSCOV001-W	Diln Fac:	5.000
Type:	Serial Dilution	Batch#:	161484
MSS Lab ID:	219122-001	Sampled:	03/30/10
Lab ID:	QC538367	Received:	03/30/10
Matrix:	Water	Analyzed:	03/31/10

I MSS Result	🦈 🐍 🏒 MSS RL		Rësult	RL CONTRACT	% D)iff Lim
2.330	0.20	00	2.430	1.000	4	10



	Metals Anal	ytical Report.	
Lab #:	219122	Location:	IR21 Storm Sewer Flushing
Client:	CH2M Hill Constructors Inc.	Prep:	EPA 200.8
Project#:	264204.16.A4.04	Analysis:	EPA 200.8
Type:	BLANK	Diln Fac:	5.000
Lab ID:	QC538563	Batch#:	161529
Matrix:	Water	Prepared:	03/31/10
Units:	ug/L	Analyzed:	04/01/10

	Analyte	Result	RL	MDL
Arsenic		ND	1.0	0.11
Beryllium	\	ND	1.0	0.12
Cadmium		ND	1.0	0.083
Chromium		ND	1.0	0.15
Copper		ND	1.0	0.13
Lead		ND	1.0	0.15
Nickel		ND	1.0	0.11
Selenium		ND	1.0	0.15
Silver.		ND	1.0	0.068
Zinc		ND	5.0	1.1

RL= Reporting Limit

MDL= Method Detection Limit



		ytical Repo	rt
Lab #:	219122	Location:	IR21 Storm Sewer Flushing
Client:	CH2M Hill Constructors Inc.	Prep:	EPA 200.8
Project#:	264204.16.A4.04	Analysis:	EPA 200.8
Matrix:	Water	Batch#:	161529
Units:	ug/L	Prepared:	03/31/10
Diln Fac:	5.000	Analyzed:	04/01/10

Type:

BS

Lab ID:

QC538564

18 8 7	Analyte 🗼 🔆	Spiked	Result	%RE(C Limits .
Arsenic		100.0	95.95	96	73-116
Beryllium		100.0	93.90	94	61-145
Cadmium		100.0	92.70	93	77-116
Chromium		100.0	93.40	93	78-124
Copper	``	100.0	94.00	94	70-125
Lead	•	100.0	95.05	95	76-121
Nickel		100.0	94.25	94	78-128
Selenium		100.0	94.60	95	68-127
Silver		100.0	89.55	90	64-123
Zinc		100.0	97.15	97	66-124

Type:

BSD

Lab ID:

QC538565

Analyte	Spiked A	Result	%REC	Limits	RPD	Lim
Arsenic	100.0	95.30	95	73-116	1	10
Beryllium	100.0	95.90	96	61-145	2	11
Cadmium	100.0	93.75	` 94	77-116	1	10
Chromium	100.0	93.15	93	78-124	0	10
Copper	100.0	94.65	95	70-125	1	14
Lead	100.0	97.00	97	76-121	2	11
Nickel	100.0	96.00	96	78-128	2	10
Selenium	100.0	96.85	97	68-127	2	13
Silver	100.0	90.20	90	64-123	1	11
Zinc	100.0	100.8	101	66-124	4	18



	Metals Anal	ytical Report	
Lab #:	219122	Location:	IR21 Storm Sewer Flushing
Client:	CH2M Hill Constructors Inc.	Prep:	EPA 200.8
Project#:	264204.16.A4.04	Analysis:	EPA 200.8
Field ID:	IDWIR21SSCOV001-W	Batch#:	161529
MSS Lab ID:	219122-001	Sampled:	03/30/10
Matrix:	Water	Received:	03/30/10
Units:	ug/L	Prepared:	03/31/10
Diln Fac:	5.000	Analyzed:	04/01/10

Type:

MS

Lab ID:

QC538566

**Analyte	MSS Result	Spiked	Result	%REC	Limits
Arsenic	8.825	100.0	109.8	101	65-126
Beryllium	<0.1188	100.0	99.25	99	66-130
Cadmium	0.3065	100.0	97.20	97	69-118
Chromium	3.158	100.0	99.00	96	61-130
Copper	24.06	100.0	115.9	92	50-136
Lead '	33.67	100.0	130.5	97	58-126
Nickel	10.75	100.0	106.9	96	61-132
Selenium	0.4350	100.0	98.70	98	59-135
Silver	<0.06798	100.0	92.95	93	52-126
Zinc	84.75	100.0	184.2	99	44-141

Type:

MSD

Lab ID:

QC538567

- 184251 L	Analyte	Spiked	Result Result	%REC	Limits	RPD	Lim
Arsenic		100.0	105.6	97	65-126	4	28
Beryllium		100.0	97.20	97	66-130	2	22
Cadmium		100.0	95.35	95	69-118	2	21
Chromium '		100.0	96.00	93	61-130	3	32
Copper		100.0	113.1	89	50-136	2	48
Lead		100.0	127.9	94	58-126	2	25
Nickel		100.0	103.4	93	61-132	3	30
Selenium		100.0	96.10	96	59-135	3 ·	28
Silver		100.0	91.00	91	52-126	2	24
Zinc		100.0	176.3	92	44-141	4	54



	Metals Ana	ytical Report	
Lab #:	219122	Location:	IR21 Storm Sewer Flushing
Client:	CH2M Hill Constructors Inc.	Prep:	EPA 200.8
Project#:	264204.16.A4.04	Analysis:	EPA 200.8
Field ID:	IDWIR21SSCOV001-W	Diln Fac:	25.00
Туре:	Serial Dilution	Batch#:	161529
MSS Lab ID:	219122-001	Sampled:	03/30/10
Lab ID:	QC538568	Received:	03/30/10
Matrix:	Water	Analyzed:	04/01/10
Units:	ug/L		

Analyte	MSS Result	MSS RL	Re	sult 🔭 🛴	RL 🗎	% Di	ff Lim
Arsenic	8.825	1.000		8.333	2.500	6	10
Beryllium	ND	1.000	ND		2.500	NC	10
Cadmium	0.3065.	1.000	ND		2.500	NC	10
Chromium	3.158	1.000		3.215	2.500	NC	10
Copper	24.06	1.000		22.74	2.500	5	10
Lead	33.67	1.000		32.50	2.500	3	10
Nickel	10.75	1.000		11.45	2.500	6	10
Selenium	0.4350	1.000	ND		2.500	NC	10
Silver	ND	1.000	ND	•	2.500	NC	10
Zinc	84.75	5.000		87.43	16.27	3	10



		ytıcal Report	
Lab #:	219122	Location:	IR21 Storm Sewer Flushing
Client:	CH2M Hill Constructors Inc.	Prep:	EPA 200.8
Project#:	264204.16.A4.04	Analysis:	EPA 200.8
Field ID:	IDWIR21SSCOV001-W	Diln Fac:	5.000
Type:	Post Digest Spike	Batch#:	161529
MSS Lab ID:	219122-001	Sampled:	03/30/10
Lab ID:	QC538569	Received:	03/30/10
Matrix:	Water	Analyzed:	04/01/10
Units:	ug/L		

Analyte	MSS Result	Spiked	Result	%REC	Limits 💥
Arsenic -	8.825	500.0	484.6	95	75-125
Beryllium	<0.1188	500.0	506.0	101	75-125
Cadmium	0.3065	500.0	492.8	98	75-125
Chromium	3.158	500.0	465.4	92	75-125
Copper	24.06	500.0	476.4	90	75-125
Lead,	33.67	500.0	553.5	104	75-125
Nickel	1,0.75	500.0	464.7	91	75-125
Selenium	0.4350	500.0	466.6	93	75-125
Silver	<0.06798	500.0	498.2	100	75-125
Zinc	84.75	500.0	555.5	94	75-125

Page 1 of 1 100



	Total Oil	Grease (HEM)	
Lab #:	219122	Location:	IR21 Storm Sewer Flushing
Client:	CH2M Hill Constructors Inc.	Prep:	METHOD
Project#:	264204.16.A4.04	Analysis:	EPA 1664A
Analyte:	Oil & Grease (HEM)	Batch#:	161547
Field ID:	IDWIR21SSCOV001-W	Sampled:	03/30/10
Matrix:	Water	Received:	03/30/10
Units:	mg/L		

Type 🚕 L	Lab ID	Result	RL MAN	MDL	Diln Fac	Prepared	Analyzed
SAMPLE 219	9122-001	8.89	5.55	1.40	1.110	03/31/10	04/01/10
BLANK QC5	538627	ND	5.00	1.20	1.000	03/29/10	03/29/10

ND= Not Detected at or above $\mbox{\c MDL}$

RL= Reporting Limit

MDL= Method Detection Limit



	Total Oils.	Grease (HEI	M) , is i
Lab #:	219122	Location:	IR21 Storm Sewer Flushing
Client:	CH2M Hill Constructors Inc.	Prep:	METHOD
Project#:	264204.16.A4.04	Analysis:	EPA 1664A
Analyte:	Oil & Grease (HEM)	Diln Fac:	1.000
Matrix:	Water	Batch#:	161547
Units:	mg/L	Analyzed:	03/29/10

Туре	Lab ID	Spiked	Result	%REC	Limits	RPD	Lim
BS	QC538628	40.00	37.40	93	78-114		
BSD	QC538629	40.00	43.60	109	78-114	15	18



	Total	Cyanide	
Lab #:	219122	Location:	IR21 Storm Sewer Flushing
Client:	CH2M Hill Constructors Inc.	Prep:	METHOD
Project#:	264204.16.A4.04	Analysis:	SM4500CN-E
Analyte:	Cyanide	Batch#:	161585
Field ID:	IDWIR21SSCOV001-W	Sampled:	03/30/10
Matrix:	Water	Received:	03/30/10
Units:	mg/L	Analyzed:	04/02/10
Diln Fac:	1.000		

Type Lab ID Result	RL (MDL	
SAMPLE 219122-001 ND	0.01	0.0009	
BLANK QC538796 ND	0.01	0.0009	

ND= Not Detected at or above MDL $\,$

RL= Reporting Limit

MDL= Method Detection Limit



		Cyanide	
Lab #:	21.9122	Location:	IR21 Storm Sewer Flushing
Client:	CH2M Hill Constructors Inc.	Prep:	METHOD
Project#:	264204.16.A4.04	Analysis:	SM4500CN-E
Analyte:	Cyanide	Diln Fac:	1.000
Field ID:	IDWIR21SSCOV001-W	Batch#:	161585
MSS Lab ID:	219122-001	Sampled:	03/30/10
Matrix:	Water	Received:	03/30/10
Units:	mg/L	Analyzed:	04/02/10

Туре	Lab ID	MSS Result	Spiked	Result	%REC	Limits	RPD	Lim
LCS	QC538797		0.2000	0.2013	101	75-125		
MS	QC538798	<0.01000	0.2000	0.2037	102	75-125		
MSD	QC538799		0.2000	0.1902	95	75-125	7	20



		рĤ	
Lab #:	219122	Location:	IR21 Storm Sewer Flushing
Client:	CH2M Hill Constructors Inc.	Prep:	METHOD
Project#:	264204.16.A4.04	Analysis:	EPA 9040C
Analyte:	рН	Diln Fac:	1.000
Field ID:	IDWIR21SSCOV001-W	Batch#:	161473
Lab ID:	219122-001	Sampled:	03/30/10 10:15
Matrix:	Water	Received:	03/30/10
Units:	SU	Analyzed:	03/30/10 18:05

Result	RL Company	
6.9	1.0	



		рН		
Lab #:	219122	Location:	IR21 Storm Sewer Flushing	g
Client:	CH2M Hill Constructors Inc	. Prep:	METHOD	
Project#:	264204.16.A4.04	Analysis:	EPA 9040C	
Analyte:	рН	Units:	SU	
Field ID:	IDWIR21SSCOV001-W	Diln Fac:	1.000	
Type:	SDUP	Batch#:	161473	
MSS Lab ID	219122-001	Sampled:	03/30/10 10:15	
Lab ID:	QC538307	Received:	03/30/10	
Matrix:	Water	Analyzed:	03/30/10 18:05	

MSS Result	::"	Result	11/2 mg/s ²	RL		RPD	Lim	120	 772	.3%
6.880		6.870		1.00	0	0	1			



and the second distribution of the second distri	Phenolic	Compounds	The second secon	
Lab #:	219122	Location:	IR21 Storm Sewer Flushing	
Client:	CH2M Hill Constructors Inc.	Prep: '	METHOD	
Project#:	264204.16.A4.04	Analysis:	EPA 420.1	
Analyte:	Phenolic Compounds	Batch#:	161550	
Field ID:	IDWIR21SSCOV001-W	Sampled:	03/30/10	
Matrix:	Water	Received:	03/30/10	
Units:	mg/L	Prepared:	04/01/10	•
Diln Fac:	1.000	Analyzed:	04/02/10	

<i>,</i> Туре	Lab ID	🤻 🥜 Result	h=-	RL:::	 MDL ***	and the second second
SAMPLE	219122-001	ND		0.050	0.011	
BLANK	QC538640	· ND		0.050	0.011	

 ${\tt ND=}$ Not Detected at or above MDL

RL= Reporting Limit

MDL= Method Detection Limit



		Compounds	
Lab #:	219122	Location:	IR21 Storm Sewer Flushing
Client:	CH2M Hill Constructors Inc.	Prep:	METHOD
Project#:	264204.16.A4.04	Analysis:	EPA 420.1
Analyte:	Phenolic Compounds	Batch#:	161550
Field ID:	IDWIR21SSCOV001-W	Sampled:	03/30/10
MSS Lab ID:	219122-001	Received:	03/30/10
Matrix:	Water	Prepared:	04/01/10
Units:	${ t mg/L}$	Analyzed:	04/02/10
Diln Fac:	1.000		

҉҉Тур∈	e 🔠 Lab. ID	MSS Result	Spiked	Result	%REC	Limits	RPD Lim
LCS	QC538641		1.000	0.9598	96	73-109	
MS	QC538642	<0.05000	1.000	0.9966	100	1-174	
MSD	QC538643		1.000	. 1.031	103	1-174	3 36

VALLEJO SANITATION & FLOOD CONTROL DISTRICT SPECIAL WASTEWATER DISCHARGE PERMIT

ISSUED TO:

CH2MHILL - John Blasco - Jeff Paik

DESCRIPTION OF PERMITTED DISCHARGE:

Less than 10,000 gallons of treated wastewater from flushing the storm system at Bldg. 386. Discharging into a sanitary sewer manhole on the "southwest" corner of Bldg. 386 Ml.

EFFECTIVE DATE:

EXPIRATION DATE:

INSPECTOR:

04/06/10

05/06/10

K. Barnett

The above named permittee is hereby authorized to discharge wastewater to the Vallejo Sanitation and Flood Control District sanitary sewer system. This discharge will be in accordance with the Standard Terms and Conditions of this permit. See reverse.

The permittee shall report to the District's Pollution Control Department any changes (permanent or temporary) in operations that may significantly change the quantity and/or quality of the discharge.

This permit is not transferable to any other organization or owner. Any change in ownership will require a new application to be completed and a new permit issued.

This permit is subject to revocation for reasons of falsification or violation of the terms of this agreement or other applicable regulations.

AGREEMENT TO COMPLY

Lagree to be bound by and comply with each and every provision of this permit and Lunderstand, acknowledge, and agree that this permit is a binding agreement enforceable in a court of law.

Lalso agree that this discharge permit may be terminated by the District as a consequence of my failure to comply with the terms and conditions stated berein.

I understand that no part of this permit may be assigned or transferred without prior written consent of the Vallejo Sanitation and Flood Control District and that I shall defend, indemnify and hold harmless the Vallejo Sanitation and Flood Control District, its officers, employees and agents against any claim, loss or liability arising out of this agreement due to my own willful or negligent acts or omission(s). I further agree to comply with all applicable laws, ordinances, codes and regulations of the Federal, state and local governments. I certify that I am fully authorized and competent to enter this agreement on behalf of the person, company, entity or organization that I represent.

Signature:

Toh C. Blenco

Date: /

April 7, 2010

Supporting lab report is located:

k:\pcd\files\bustype\specialdischargepermits\CH2MHILL\bldg386stormflushing\bldg386permit

STANDARD TERMS AND CONDITIONS FOR SPECIAL WASTEWATER DISCHARGES

- 40 CFR Part 136 methods must be used and must demonstrate compliance with the discharge limit. The analyst(s) initials must be included with results.
- 2. No person shall discharge wastewater with a pH below 6.0 or above 9.0.
- No person shall discharge any liquid or waste containing more than 100 mg/L of petroleum based oil and grease, or containing any fat, oil, grease or other substance that will become solid or visibly viscous at temperatures between 0 degrees and 60 degrees Centigrade.
- 4. Discharge to the sanitary sewer shall be conducted at the entry point approved by the District. Discharge to any other location is prohibited.
- Discharge at a rate which causes an hydraulic overload of the sanitary sewer system is strictly prohibited.
- 6. The permittee shall make every effort to reduce or mitigate any odors resulting from the discharge of wastewater to the sanitary sewer system.
- 7. The District shall inspect the facilities at the address of the discharge to ascertain whether all requirements, terms and conditions of wastewater discharge are being complied with. Persons or occupants of the premises where wastewater is being created or discharged shall allow duly appointed District personnel ready access at all reasonable times to all parts of the premises for the purpose of inspection, sampling, or the performance of any of their duties. The District, or its designated representatives, shall have the right to examine and copy those records necessary to fulfill any of their duties.
- 8. A discharge permit is subject to revocation for reasons of fatsification of data, violation of the terms of agreement, or other applicable regulations. The District may also fine the permit holder a minimum of \$1000 per day for each violation of wastewater discharge requirements.
- The permittee shall maintain any pretreatment units on a regular basis as stipulated in the manufacturer's specifications. A file which documents all maintenance activity, shall be available to the District within 24 hours of the initial request.
- Spills to the sanitary sewer or the storm collection system shall be immediately reported to the District at (707) 644-8949. A written report shall be submitted to the District within 10 calendar days. The report shall describe the event, the start time, the specific source, quantity discharged, the point of entry to the sanitary sewer or storm collection system; the time the spillage ceased and steps taken to prevent another incident.
- 11. The discharge of non-stormwater discharges to the District's storm drain system or to any public drainage system that drains to the District's storm drain system is prohibited.
- 12. In order to prevent pollution of the storm drain, the permittee shall implement and maintain good housekeeping practices. No equipment washing shall be permitted at this location.
- 13. The District reserves the right to direct the permittee to cease the discharge at any time during the discharge period.

Appendix D Waste Profile and Waste Disposal Manifest

UNIFORM I	IAZARDOUS	1. Generator ID Number		2. Page 1 of	3. Emergency Response		4. Manifest	racking No	imber 263		
5. Generator's	Name and Mail	no Address			Generator's Site Address				<u> </u>		
ALL WALL	NR MAII NENSO P	THE THE AND A	. C .			· .	•			•	
		1 244 2 89		1							
6. Transporter	1 Company Nan	ne					U.S. EPA ID N			31	
									+ 15	3 8 61	
7. Transporter	2 Company Nan	79					U.S. EPA ID N	umber			
8. Designated	Facility Name ar	nd Site Address		**************************************			U.S. EPA ID N	lumber			
2.50	رگزیز (انجازی از این داری در در در در	NO SIDE MODIFIES STATE OF THE S	0. である (1. あま)	****			An.	(30	+ 15	276	
Facility's Pho	ne: 🛂 🖰	And State						r******			
).S. DOT Descript Packing Group (if	tion (including Proper Shipping Nar anvi)	ne, Hazard Class, ID Numbe	er,	10. Contai No.	ners Type	11. Total Quantity	12. Unit Wi./Vol.	13. v	Vaste Codes	j
3 - """		ROBA MATA	10 30 to 10 to 10 to	15 31 64	140	· iype	downer		<i>i</i> ; { }	T	
,	i de la compania de l					3 64		$ \forall $		·	· · · · · · · · · · · · · · · · · · ·
	·			·····	001	10 / X	1 4 (3)				
2.			•							3.000	

3.						 	<u> </u>	 	 		
	•				j]		
- 1		•							-		
4.	** ** ** ** ** ** ** ** ** ** ** ** **		<u></u>								
											*
						<u> L</u>	<u> </u>	<u> </u>	i		
	•	ons and Additional Information	3 P - 1	•	P. C. S. S. S.	, i			OL B		
1 25	ì				:•	1	6 ·		į		
					Dan Tak	₹S :					
marked Exporter I certify	and labeled/place r, I certify that the that the waste mi	OR'S CERTIFICATION: I hereby of greed, and are in all respects in pro- contents of this consignment conf- nimization statement identified in 4	oper condition for transport a form to the torms of the attac	according to appli ched EPA Acknow large quantity ger	icable international and nat vledgment of Consent nerator) or (h) (if I am a sm	tional governn	nental regulations			am the Prima	ary
	Meror's Printed/T			i I	gnature	× 11 ×	(v.s.)			/ *	Ye ∂
16. Internation	nal Shipments	<u> </u>			ey	2	. Xx.	<u> </u>			
	signature (for exp	import to U.S.	·	Export from	U.S. Port of e						
17. Transport	er Advnowledgme	nt of Receipt of Materials									
Transporter 1	Printed/Typed Na			Sig	gnature MI A	2 1	1.		Mon) Ye
Transporter 3	Printed/Typed N	RULMON			7 7 7	<u> </u>	<u>"" </u>			<u>'''</u>	1
mansponer &	. гимсогурео н	ane) 	gnature				Mor I	oth Day	Ye I
18. Discrepar	1CV										ــــا
	ancy Indication Sp	pace Quantity	Туре		Residue	· · · · · ·	Partial Re	jection]	Full Reje	ection
		<u> </u>		-	Manifest Reference	e Number:					
18b. Alternate	Facility (or Gene	erator)					U.S EPAID	Number			
Canicale Os		•					ı				
Facility's Pho 18c. Signatur		cility (or Generator)							Mo	nth Day	,
•		• • • • • • • • • • • • • • • • • • • •									ı
19. Hazardou	is Waste Report I	Management Method Coxies (i.e., o	codes fo: hazardous waste t	treatment, dispos	al, and recycling systems)	******			-	L	
1.		2.		3.	, , , , , , , , , , , , , , , , , , , ,		4.		. , , , , , , , , , , , , , , , , , , ,		
20. Designate	od En Zhi Ostania	as Casadau Cadifadias of masis	ot of hazardous materials co	word by the mar	Stant avecation acted in its	om 18a					
		or Operator. Certification of recest				300 100					
Printed/Typed		or Operator, Cortification of recess	7 3 70 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		gnature	311 104			Mo	nth Day	Ye



WASTE MATERIAL PROFILE SHEET

Clean Harbors Profile No. CH441486B

A. GENERAL INFORMATION GENERATOR EPA ID #/REGISTRATION # GENERATOR CODE (Assigned by Clean Harbors) ADDRESS 900 Walnut Avenue CUSTOMER CODE (Assigned by Clean Harbors) ADDRESS 4721 Tidewater Avenue Suite D		LE1713 C	CITY	Vallejo STATE/F OMER NAME: Innovati		Mare Island PROVINCE PHONE: (70 tive Construct PROVINCE	CA ZIP/POS	Norca	3403 <u>2</u> 1	
B. WASTE DESCRIPTION WASTE DESCRIPTION:	IR-21 Storm Sewer	Cleaning Sediments Bldg. 3	386,38	8, 390						
PROCESS GENERATING V	VASTE (Please provide	detailed description of process ge	enerating	g waste):						
Storm Sewer Cleaning	Sediments from Blo	lg. 386,388, 390 Waste solid	ls from	dewatering of w	vash wate	rs				
C. PHYSICAL PROPERTIES	3 (at 25C or 77F)			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	·	T				
PHYSICAL STATE SOLID WITHOUT FREE	LIQUID	NUMBER OF PHASES/LAYE 1 2 3	ERS TOP	0.00		1 '	If liquid present) e.g. Water)		COLOR	
POWDER		% BY VOLUME (Approx.)	MIDE				(e.g. Motor Oil)		<u>brown</u>	
MONOLITHIC SOLID LIQUID WITH NO SOLII	DS	% BY VOLUME (Approx.)	вот				000 (e.g. Molasses	.)		
LIQUID/SOLID MIXTUR % FREE LIQUID	E		$\overline{}$			> 10,000	-			ı
% SETTLED SOLID		ODOR NONE		BOILING POINT °	F (°C)	MELTING PO	OINT °F (°C)	тот/	AL ORGANIC	\dashv
% TOTAL SUSPENDE SLUDGE	.D SOLID	MILD		<= 95 (<=35)		·		CAR		.
GAS/AEROSOL		STRONG	1	95 - 100	(35-38)		0 (<60) 200 (60-93)		<= 1%	1
		Describe:	Ì	101 - 12	9 (38-54)	> 200 (>93)		1-9%		1
		L		>= 130 ((>54)		0 (>93)		>= 10%	
FLASH POINT °F (°C)	рН	SPECIFIC GRAVITY		ASH-	•		BTU/LB (MJ/kg)			
< 73 (<23)	· <= 2	< 0.8 (e.g. Gasoline)		< 0.1		> 20	< 2,000 (·	<4.6)		
73 - 100 (23-38)	2.1 - 6.9	0.8-1.0 (e.g. Ethanol)		ست 0.1 - 1.0		Unknown	2,000-5,0	00 (4.6-	11.6)	
101 -140 (38-60)	7 (Neutral)	1.0 (e.g. Water)		1.1 - 5.0			5,000-10,	,000 (11	.6-23.2)	
141 -200 (60-93)	7.1 - 12.4	1.0-1.2 (e.g. Antifreeze)	1.0-1.2 (e.g. Antifreeze) 5.1 - 20.0				> 10,000 (>23.2)			
> 200 (>93)	>= 12.5	> 1.2 (e.g. Methylene Chlo	oride)				Actual:			
		on of the waste, include any inert on S. Please do not use abbreviation		ents and/or debris. F	Ranges for i	ndividual comp	onents are accepta	ble. If a	trade name is	
CHEMICAL			,				MIN		MAX	UOM
СНКОМІИМ							4.3400000		4.3400000	PPM
DEBRIS (PAPER,PLAS							0.0000000		15.0000000	%
LEAD							22.2000000		22.2000000	PPM
PCB							500.0000000	5	00.0000000	PPB
SOIL							95.0000000	1	00.0000000	%
	ED HOSE >12" LONG,	GE METAL DEBRIS OR OTHER METAL WIRE >12" LONG, META						2" [YES .	NO
If yes, describe, incl	uding dimensions:	paper, plastic, wood debris < 1'				•				
DOES THIS WASTE CONT	TAIN ANY METALS IN F	POWDERED OR OTHER FINELY	/ DIVIDE	ED FORM?	ţ				YES 🛂	NO
	CAL WASTE, PATHOLO	ACTED ANY OF THE FOLLOWIN OGICAL WASTE, HUMAN OR ANI							YES 🔽	NO
		either infectious nor does it contain elect the answer below that applie		ganism known to be	a threat to	human health.	This certification is			
The waste was never	er exposed to potentially	v infectious material.				*			VES	NO

Chemical disinfection or some other form of sterilization has been applied to the waste.

I ACKNOWLEDGE THAT MY FRIABLE ASBESTOS WASTE IS DOUBLE BAGGED AND WETTED.

SPECIFY THE SOURCE CODE ASSOCIATED WITH THE WASTE: G44

I ACKNOWLEDGE THAT THIS PROFILE MEETS THE CLEAN HARBORS BATTERY PACKAGING REQUIREMENTS.

YES

YES

SPECIFY THE FORM CODE ASSOCIATED WITH THE WASTE.

NO

NO

NO



Clean Harbors Profile No. CH441486B

	NST		

								_
Are	these	values	based	on t	estina	or kn	owledge	7

Knowledge Testing

If based on knowledge, please describe the rationale applied to identify and characterize the waste material (ex., include reference to Material Safety Data Sheets, process considerations, operating procedures).

Please indicate which constituents below apply. Concentrations must be entered when applicable to assist in accurate review and expedited approval of your waste profile. Please note that the total regulated metals and other constituents sections require answers.

RCRA	REGULATED METALS	REGULATORY LEVEL (mg/l)	TCLP mg/l	TOTAL	UOM	NOT APPLICABLE	
D004	ARSENIC	5.0	J	8.2000000	PPM		
D005	BARIUM	100.0	. .	130.0000000	PPM		
D006	CADMIUM	1.0		3.3000000	РРМ		
D007	CHROMIUM	5.0		120.0000000	РРМ		
D008	LEAD	5.0		370.0000000	PPM		
D009	MERCURY	0.2		0.5800000	PPM	•••••	
D010	SELENIUM	1.0		0.7500000	РРМ		
D011	SILVER	5.0		0.4600000	PPM		
• • • • • •	VOLATILE COMPOUNDS			OTHER CONSTITUEN		MAX UOM	NOT
D018	BENZENE	0.5		OTHER CONSTITUE	113	WAX CON	APPLICABLE
D019	CARBON TETRACHLORIDE	0.5		BROMINE			≥
D021	CHLOROBENZENE	100.0	·	CHLORINE			V
D022	CHLOROFORM	6.0		FLUORINE			V
D028	1,2-DICHLOROETHANE	0.5	`	IODINE			• • • • • • • • • • • • • • • • • • •
D029	1,1-DICHLOROETHYLENE	0.7		SULFUR			· 💆 · · · ·
D035	METHYL ETHYL KETONE	200.0		POTASSIUM			····· 💆 ·····
D039	TETRACHLOROETHYLENE	0.7		SODIUM			······ 💆 ·····
D039	TRICHLOROETHYLENE	0.5		AMMONIA.	.`		7
		0.2		CYANIDE AMENABLE			····· 💆 ·····
D043	VINYL CHLORIDE			CYANIDE REACTIVE		• • • • • • • • • • • • • • • • • • • •	· 💆
	SEMI-VOLATILE COMPOUNDS			CYANIDE TOTAL			······
D023	ò-CRESOL	200.0				• • • • • • • • • • • • • • • • • • • •	····· 🗐 ·····
D024	m-CRESOL	200.0		SULFIDE REACTIVE			<u> </u>
D025	p-CRESOL	200.0		HOCs		PCBs	
D026	CRESOL (TOTAL)	200.0		NONE		NONE	
D027	1,4-DICHLOROBENZENE	7.5		< 1000 PPM		✓ < 50 PPM	
D030	2,4-DINITROTOLUENE	0.13	. .	>= 1000 PPM		>=50 PPM	
D032	HEXACHLOROBENZENE	0.13				IF PCBS ARE PRESEN	T IS THE
D033	HEXACHLOROBUTADIENE	0.5				WASTE REGULATED	
D034	HEXACHLOROETHANE	3.0				CFR 761?	
D036	NITROBENZENE	2.0		I		YES 💽	NO
D037	PENTACHLORÓPHENOL	100.0					
D038	PYRIDINE	5.0					
D041	2,4,5-TRICHLOROPHENOL	400.0					
D042	2,4,6-TRICHLOROPHENOL	2.0					
	PESTICIDES AND HERBICIDE	S					
D012	ENDRIN	0.02					1
D013	LINDANE	0.4					
D014	METHOXYCHLOR	10.0					
D015	TOXAPHENE	0.5					
D016	2,4-D	10.0					
D017	2,4,5-TP (SILVEX)	1.0		, e			
D020	CHLORDANE	0.03					
D031	HEPTACHLOR (AND ITS EPOXIDE) 0.008					
	AL HAZARDS						

ADDITIONAL HAZARDS

DOES THIS WASTE HAVE ANY UNDISCLOSED HAZARDS OR PRIOR INCIDENTS ASSOCIATED WITH IT, WHICH COULD AFFECT THE WAY IT SHOULD BE HANDLED?

YES NO (If yes, explain)

CHOOSE ALL THAT APPLY

DEA REGULATED SUBSTANCE EXPLOSIVE FUMING OSHA REGULATED CARCINOGENS
POLYMERIZABLE RADIOACTIVE REACTIVE MATERIAL NONE OF THE ABOVE



Clean Harbors Profile No. CH441486B

F. RE	GULAT	ORY STAT	ับร					•				
	YES	☑ NO	USEPA HAZARDO	ous w	ASTE?							
l V	VEC	NO	DO ANY STATE I	DO ANNOTATE MARTE CODES APPLYS								
	YES	NO	D DO ANY STATE WASTE CODES APPLY? 611									
,			L				*					
	YES	₩ NO	Texas Waste Cod		NUNCIAL 1	MACTE CODEC ADDI VO			*			
	TES	ET I NO	DO ANT CANADI.	AN PRO	VINCIAL	VASTE CODES APPLY?						
	YES	✓ NO	IS THIS WASTE F	ROHIB	ITED FRO	M LAND DISPOSAL WITH	OUT FURTHER TREAT	MENT PE	ER 40 CFR PART 268?			
			LDR CATEGO		Not sub	ect to LDR		•				
l		Aug to y	VARIANCE IN	FO:								
	YES	Y NO	IS THIS A UNIVE	RSAL W	ASTE?							
	YES	Y NO	IS THE GENERA	TOR OF	THE WAS	TE CLASSIFIED AS CON	DITIONALLY EXEMPT	SMALL QI	UANTITY GENERATOR (CESQG)?			
1	YES	NO	IS THIS MATERIA	AL GOIN	IG TO BE I	MANAGED AS A RCRA EX	EMPT COMMERCIAL	PRODUCT	T, WHICH IS FUEL (40 CFR 261.2 (C)(2)(II))?			
	YES	V. NO	DOES TREATME	NT OF	THIS WAS	TE GENERATE A F006 OF	R F019 SLUDGE?		•			
•	YES	NO	IS THIS WASTES	STREAM	M SUBJEC	T TO THE INORGANIC ME	TAL BEARING WASTE	PROHIB	ITION FOUND AT 40 CFR 268.3(C)?			
	YES	✓ NO	DOES THIS WAS	TE CON	NTAIN VO	S IN CONCENTRATIONS	5 >=500 PPM?					
	YES	NO	DOES THE WAS	TE CON	ITAIN GRE	ATER THAN 20% OF ORG	SANIC CONSTITUENTS	S WITH A	VAPOR PRESSURE >= .3KPA (.044 PSIA)?			
•	YES	✓ NO	DOES THIS WAS	TE CON	NTAIN AN	ORGANIC CONSTITUENT	WHICH IN ITS PURE I	FORM HAS	S A VAPOR PRESSURE > 77 KPA (11.2 PSIA)?			
	YES	,										
					•	PERFUND) WASTE?	CLAD DUI ECO					
l	YES	₩ NO				OF THE FOLLOWING NE			W () 1000			
			Hazardous (Organic	NESHAP (HON) rule (subpart G)	Pharmaceut	icals produ	uction (subpart GGG)			
1	YES	NO	IF THIS IS A US E	PA HA	ZARDOUS	WASTE, DOES THIS WAS	STE STREAM CONTAI	N BENZEN	NE?			
		YES							tene NESHAP or is this waste regulated under the benzeneing, coke by-product recovery, or petroleum refinery process?			
•		YES				this waste stream a facility						
			ne TAB quantity for y		· .	-	gagram/year (1 Mg = 2,		y > 10 Mg/year:			
					•	the Waste Or Test Data	gagrannyour (1 mg = 2,	200 103)	Knowledge Testing			
ĵ			the knowledge :			***************************************	***************************************					
G DC	типс	INFORMA										
ŀ			PPING NAME:									
DO 17				IS WA	STE SOL	IDS, (LEAD), N/A						
					01L 00L	ibo, (EEAD), WA			<u> </u>			
			I REQUIREMENTS. T FREQUENCY	ONE	TIME W	EEKLY MONTHLY Q	UARTERLY YEARL	Y OTH	ER			
		C	ONTAINERIZED				III K I IOIIID		BULK SOLID			
•	0-0		ERS/SHIPMENT				ULK LIQUID		J. J. John Collin			
stc	RAGE	CAPACITY:				GALLONS/SHIPMENT:	0 Min -0 Max	GAL.	SHIPMENT UOM: YARD			
CON		R TYPE:	V						TONS/YARDS/SHIPMENT: 3.00 Min - 5.00 Max			
,		JBIC YARD				••						
	: ОТ	TE TANK HER:	DRU	М					i i			
] :Y	j o.		DRUM SIŻE						1			
I. SPE	CIAL R	EQUEST	······································									
		TS OR REC				•						
Re	port 72	2980, sam	ple ID WB001									
												
		R'S CERTIF		ad in this	and attac	ned documents is correct to	the hest of my knowle	dae Lalea	a cortify that any samples			
sub	mitted a	are represe	ntative of the actual	waste. I	if Clean Ha	rbors discovers a discrepa	ncy during the approval	process, C				
Cle	an Harl	pors the aut	hority to amend the p	orofile, a	s Clean H	arbors deems necessary, to	reflect the discrepancy	<i>/</i> .	· ·			
ļ			ED SIGNATURE		K.	AME (PRINT)		TITLE	DATE			
_	•		SIGNATURE		, 14,	ZIAIT (LIVIIAL)		IIILE	5.002			
<u> </u>					-	(